

# Table Of Contents

<b>Preface</b>	<b>1</b>
<i>Chapter 1 Statistical Process Control (SPC)</i>	7
<i>Chapter 2 Measurement</i>	27
<i>Chapter 3 Control Charting</i>	53
<i>Chapter 4 Reading a Control Chart</i>	67
<i>Chapter 5 Using a Control Chart</i>	77
<i>Chapter 6 Good Tools Misused</i>	87
<i>Chapter 7 Tools for Running Your Machine</i>	97
<i>Chapter 8 Running Your Machine with SPC</i>	129
<i>Chapter 9 Benefits of Running Your Machine with SPC</i>	157
<i>Appendix A Control Chart Calculations</i>	165
<i>Appendix B Plotting Control Chart Data</i>	171
<i>Appendix C Glossary</i>	173
<b>Index</b>	<b>177</b>