

Table of Contents

Chapter 11-SPC IMPLEMENTATION ISSUES	1
Introduction	1
Getting SPC Started	2
Consultant's Report to Superiority Corporation	3
Management organization	
Full-scale implementation	
Strategic quality planning	
Manufacturing Implementation	5
Control charts	
Core team	
Core team training	
Core team membership	
Project plan	
Pilot project	
Process capability analysis	
Management Review	
Selecting performance indicators.....	10
Variables versus attributes performance indicators	
Guidelines for selecting process control indicators	
Guidelines for implementing SPC using variables data	
Option A: Moving X charts	
Option B: Individuals charts (X charts)	
Option C: Median control charts	
Guidelines for choosing an SPC method for attributes data.....	16
Process sampling	
Subgroups with too little variation	
Detecting subgrouping problems	
Automated versus manual sampling	
How many? How often?	
Evaluating the effectiveness of SPC	23
Offline analysis of control charts	24
Ad hoc SPC (The Art of Winging It)	
Computers for SPC	
SPC for special applications	
References	
Chapter 12-MEASUREMENT ERROR	33
Evaluation of measurement error.....	33
Definitions	
Evaluating measurement systems	36
Evaluating accuracy (calibration)	
How to determine accuracy	
Interpretation	
Calibration example	
Interpretation of example	
Evaluating measurement error using control charts	
Pointers for using measurement error control charts	
Computing the percent of error	

Example	
References	
Chapter 13-PROCESS CAPABILITY ANALYSIS	52
Process capability analysis.....	52
How to perform process capability studies — A 10 step plan.....	54
Statistical analysis of process capability data.....	57
Control chart method: attributes data.	
Control chart method: variables data.	
Interpreting capability indices	
Non-normal distributions	64
Skewed distributions	
Yields of skewed distributions	
Folded normal distributions	
Folded normal yields	
True position.....	71
Example	
Probability paper	75
Probability paper example	
Related techniques	
Pointers for using probability plots	
References	
Chapter 14-MEDIAN CONTROL CHARTS	79
Introduction	79
How to prepare and analyze charts	
Interpretation of charts	
Example	
Related techniques	
Range control cards	
Pointers for using charts	
References	
Chapter 15-Process Control For Short And Small Runs	91
Introduction	91
Strategies for Short and Small Runs	92
Preparing the Short Run Process Control Plan (PCP).....	93
Process Audit	
Selecting Process Control Elements	
Example One	
Example Two	
The Single Part Process	
Other Elements of the PCP	
Short Run SPC Techniques	
Variables Data	99
Exact method of computing control limits for short and small runs	
Code Value Charts	
Stabilized Control Charts for Variables	
Attribute SPC for Small and Short Runs	111
SPC of Attributes Data from Short Runs	
Stabilized Attribute Control Charts	

Demerit Control Charts	
Simplified Quality Score Charts	
Conclusion	
Chapter 16-CUMULATIVE SUM (CUSUM) CHARTS	121
Introduction	121
Combined plan	
Procedure	
How to use the cusum chart	
Example	
Guidelines	
Chapter 17-SPC FOR CONTINUOUS AND BATCH PROCESSES	136
Introduction	136
Continuous or batch versus discrete processes	137
Statistical obstacles	138
Statistical alternatives for continuous or batch processes	
Two-way Control Charts	
Examples	146
Bottling	
Extrusion and coating	
Distillation	
Chapter 18-SPC FOR AUTOMATED MANUFACTURING	151
Introduction	151
SPC techniques for automated manufacturing	152
Problems with traditional SPC techniques	
Special and common cause charts	
EWMA common cause charts	
Example	
EWMA control charts	
Choosing the value of	
Special cause charts	
SPC and automatic process control	
Chapter 19-SPC FOR SERVICES AND ADMINISTRATION	165
Introduction	165
Unique service industry characteristics	
Lessons from manufacturing	
Measuring service quality	170
Deciding where to measure	
Deciding what to measure	
How to measure service quality	174
Surveys and sampling	
A self-administered survey method that works	
Questionnaire design	
Survey implementation	
ASQC survey of service quality	
When should we measure service quality?	180
Analyzing service quality data	181
Control charts of time-based performance measures	

A case study in non-manufacturing SPC	184
SPC control charting in the service industries	185
Introduction	
Applications	
Conclusion	
Quality improvement	194
A common pitfall	
References	
Chapter 20-SPC FOR PROCESSES WITH LINEAR DRIFT	197
Introduction	197
Examples	
SPC and linear drift	200
Control charts for linear trends	
How much drift should be allowed?	
Example of computing allowable drift	
References	
Chapter 21-SPC FOR MULTIPLE STREAM PROCESSES	208
Introduction	208
Analyzing multiple-stream processes	
The group control chart	
Implementing group control charts	
Using the group control chart when all streams are not the same	
References	
Chapter 22-PROCESS CONTROL PLANNING	216
Introduction	216
Identifying key process elements	
Preparing the process control plan	
Example of process control planning	
Contingency planning	
Process improvement planning	
References	
Appendix	228