

TABLE OF CONTENTS

PART I

INTRODUCTION

CHAPTER I

Characteristics of a Controlled Quality.....	PAGE
What is the Problem of Control?—Nature of Control—Definition of Control.	3

CHAPTER II

Scientific Basis for Control	9
Three Important Postulates—When do Fluctuations Indicate Trouble?—Evidence that Criteria Exist for Detecting Assignable Causes—Rôle Played by Statistical Theory—Conclusion.	

CHAPTER III

Advantages Secured through Control.....	26
Reduction in the Cost of Inspection—Reduction in the Cost of Rejections—Attainment of Maximum Benefits from Quantity Production—Attainment of Uniform Quality Even though Inspection Test is Destructive—Reduction in Tolerance Limits—Conclusion.	

PART II

WAYS OF EXPRESSING QUALITY OF PRODUCT

CHAPTER IV

Definition of Quality.....	37
Introductory Note—Popular Conception of Quality—Conception of the Quality of a Thing as a Set of Characteristics—Conception of the Quality of a Thing as an Attribute—Quality of a Number of the Same Kind of Things—Quality of Product: Distribution of Quality Characteristics, Quality Statistics, Quality Rate—Quality as a Relationship—How Shall Quality be Defined?	

CHAPTER V

The Problem of Presentation of Data	PAGE 55
Why We Take Data—The Problem of Presentation—Essential Information Defined—Statement of the General Problem—True versus Observed Quality.	

CHAPTER VI

Presentation of Data by Tables and Graphs	63
Presentation of Ungrouped Data—Presentation of Grouped Data—Choice of Cell Boundaries—Conclusion.	

CHAPTER VII

Presentation of Data by Means of Simple Functions or Statistics.	71
Simple Statistics to Be Used—Fraction p Defective or Non-Conforming—Arithmetic Mean \bar{X} as a Measure of Central Tendency—The Standard Deviation σ as a Measure of Dispersion—Skewness k —Flatness β_2 —Calculation of Statistics: Errors of Grouping, Number of Figures to be Retained—Measures of Relationship—Other Statistics.	

CHAPTER VIII

Basis for Determining How to Present Data	85
The Problem—Statistics to be Used When Quality is Controlled—Why the Average \bar{X} and Standard Deviation σ Are Always Useful Statistics—Tchebycheff's Theorem—Importance of Skewness k and Flatness β_2 —Conclusion.	

CHAPTER IX

Presentation of Data to Indicate Relationship	99
Two Kinds of Relationship: Functional and Statistical—Observed Relationship—Information Given by the Correlation Coefficient—Relationship between Several Qualities—Measure of Relationship, Correlation Ratio—Measure of Relationship, General Comments.	

PART III

BASIS FOR SPECIFICATION OF QUALITY CONTROL

CHAPTER X

Laws Basic to Control	121
Control—Exact Law—Law of Large Numbers—Point Binomial in Relation to Control—Evidence of the Existence of the Law of Large Numbers: Tossing a Coin or Throwing Dice, Sampling Experiment, Distribution of Number of Alpha Particles, Macroscopic Properties of Matter—Controlled or Constant System of Chance Causes—Meaning of Cause—Variable System of Chance Causes—Statistical Laws—Exact and Statistical Laws, A Comparison—Summary.	

CONTENTS

xi

CHAPTER XI

Statistical Control	PAGE 145
Conditions for Control—Necessary and Sufficient Conditions for Statistical Control.	

CHAPTER XII

Maximum Control	150
Maximum Control Defined—Characteristics of Maximum Control—Molecular Phenomena—Necessary Conditions for Maximum Control—Simple Cause System—Necessary Conditions, Some Criticisms—Some Practical Conclusions.	

PART IV

SAMPLING FLUCTUATIONS IN QUALITY

CHAPTER XIII

Sampling Fluctuations	163
Sample—Sampling Fluctuations—Simple Illustration of Sampling Fluctuations—Sampling Fluctuations in Simple Statistics—Simple Problem in Prediction of Sampling Fluctuation, Problem of Distribution—Relation of Sample to Universe—The Problem of Determining the Allowable Variability in Quality from a Statistical Viewpoint.	

CHAPTER XIV

Sampling Fluctuations in Simple Statistics under Statistical Control	174
Method of Attack—Fraction Defective—Average, Normal Universe—Average, Non-Normal Universe—Standard Deviation, Normal Universe—Standard Deviation, Non-Normal Universe—Variance—Ratio $z = \frac{\bar{X} - \bar{X}_0}{\sigma}$, Normal Universe—Distribution of Average and Standard Deviation—A Word of Caution—Skewness k and Flatness β_2 —Other Measures of Central Tendency—Other Measures of Dispersion—Chi Square—Summary.	

CHAPTER XV

Sampling Fluctuations in Simple Statistics, Correlation Coefficient	214
Correlation Coefficient—Distribution Function of Correlation Coefficient—Standard Deviation σ_r of Correlation Coefficient—Modal and Expected Values of Correlation Coefficient—Transformed Distribution of Correlation Coefficient—Conditions under Which Distribution of r Has Significance—Commonness of Causation Measured by r —Simple Example Showing How Correlation Coefficient Measures Commonness of Causation—Interpretation of r in General.	

CHAPTER XVI

Sampling Fluctuations in Simple Statistics, General Remarks	230
---	-----

Two Phases of Distribution Theory: Mathematical Distribution, Objective Distribution—Importance of Distribution Theory—Mathematical Distribution Theory, Method of Attack: Some Numerical Results, Comparison of the Two Methods—Mathematical Distribution Theory, Important Results—Mathematical Distribution Theory, Present Status—Importance of Distribution Theory—Further Comments.

PART V

STATISTICAL BASIS FOR SPECIFICATION OF STANDARD QUALITY

CHAPTER XVII

Design Limits on Variability.....	249
-----------------------------------	-----

Tolerances—Tolerances Where 100 Per Cent Inspection Cannot be Made—Importance of Control in Setting Economic Tolerance—Tolerances Where 100 Per Cent Inspection Cannot be Made, Importance of Control—Tolerance for Quality of Finished Product in Terms of Tolerances of Piece-Parts—The General Problem of Setting Tolerances on Controlled Product—Design for Minimum Variability.

CHAPTER XVIII

Specification of Standard Quality.....	262
--	-----

Standard Quality—Types of Specification—Importance of Specifying the Function f —Specification, Further Discussion—Conclusion.

PART VI

ALLOWABLE VARIABILITY IN QUALITY

CHAPTER XIX

Detection of Lack of Control in Respect to Standard Quality	275
---	-----

The Problem—The Basis for Establishing Control Limits—Choice of Statistic to Detect Change in Average Quality—Choice of Statistic to Detect Change in Standard Deviation—Additional Reason for Choosing the Average \bar{X} and Standard Deviation σ —Choice of Statistic to Detect Change Δr in the Correlation Coefficient r —Choice of Method of Using Statistics—Choice of Method of Using Statistics, Simple Example—Choice of Method of Using Statistics, Continued—Choice of Statistic for Detecting Change in Universe of Effects—Detection of Failure to Maintain Standard Quality.

CHAPTER XX

Detection of Lack of Control	PAGE 301
The Problem—Choice of Method of Estimating \bar{X} and σ —Choice of Test Criterion for Detecting Lack of Control—Criterion I, General—Criterion I, Attributes—Criterion I, Variables, Large Samples—Criterion I, Variables, Small Samples—Use of Criterion I, Some Comments—Criterion II.	

CHAPTER XXI

Detection of Lack of Control, Continued	321
Introductory Statement—Criterion III—Criterion IV—Criterion V —Criticism of Criterion V—Rôle of Judgment in Choice of Criteria— Sampling Inspection in Relation to Control, Attributes: <i>A Priori</i> Method, <i>A Posteriori</i> Method.	

PART VII

QUALITY CONTROL IN PRACTICE

CHAPTER XXII

Summary of Fundamental Principles.....	351
Introductory Statement—Object of Control—Physical Properties —Physical Laws—Causal Explanation—Measurement of Average \bar{X} and Standard Deviation σ : <i>A Posteriori</i> Probability Method, Maximum Likelihood Method, Empirical Method—Measurement of Average \bar{X} and Standard Deviation σ , Practical Example.	

CHAPTER XXIII

Sampling, Measurement.....	376
Place of Measurement in Control—All Measurement a Sampling Process—Good Data—Correction of Data for Constant Errors— Errors Introduced by Constant Systems of Chance Causes—Correc- tion for Constant Chance Errors of Measurement—Analysis of Bad Data—Analysis of Good Data—Minimizing Cost of Measurement, Simple Example—How Many Measurements?—Law of Propagation of Error, Practical Significance—Measurement through Statistical Relationship: Calibration, Effect of Error of Measurement, Conclu- sion, Example.	

CHAPTER XXIV

Sampling	404
Fundamental Considerations—Random Sample—Sampling for Protection—Representative Sample—Size of Sample—Sampling in Relation to Specification.	

CHAPTER XXV

The Control Program	418
---------------------------	-----

Résumé—Control in Research—Control in Design—Control in Development—Control in Commercial Production—Control in the Purchase of Raw Material—Quality Control Report.

APPENDIX I

Resultant Effects of Constant Cause Systems.....	425
--	-----

Introductory Remarks—Practical Significance of Results—Analytical Results—Economic Significance of Control from a Design Viewpoint.

APPENDIX II

Experimental Results	437
----------------------------	-----

Presentation of Original Experimental Results Useful in Obtaining an Understanding of the Fundamental Principles Underlying the Theory of Quality Control.

APPENDIX III

Bibliography.....	473
-------------------	-----

References for Parts I and III: Exact and Statistical Laws, Empirical Laws, Frequency Distribution Functions, Probability, Quality Control—References for Part II: Economics, Texts on Statistics, Curve Fitting—References for Part IV—References for Parts VI and VII: Estimation, Detecting Lack of Control—Other References: Errors of Measurement, Tables, Magazines, Mathematics, Graphical Methods.