

Contents

Preface	ix
Acknowledgments	xi
1. Introduction	1
2. SPC Basics	7
3. Control Chart Overview	15
4. Process Capability and Performance Studies	27
5. Data Collection Strategies	39
6. Selecting the Right Chart	49
7. Traditional Control Charts for Single Characteristics	55
8. Individual X and Moving Range Chart	65
9. $\bar{X}$ and Range Chart	75
10. $\bar{X}$ and s Chart	83
11. Control Charts for Similar Characteristics — The Target Charts	91
12. Target Individual X and Moving Range Chart	97
13. Target $\bar{X}$ and Range [™] Chart	107
14. Target $\bar{X}$ and s Chart	115

15. Control Charts for Small Lot Production Runs— The Short Run Charts	125
16. Short Run Individual X and Moving Range Chart	145
17. Short Run $\bar{X}$ and Range [™] Chart	153
18. Short Run $\bar{X}$ and s Chart	163
19. Charts for Multiple Characteristics—The Group Charts	175
20. Group Individual X and Moving Range Chart	183
21. Group $\bar{X}$ and Range Chart	191
22. Group $\bar{X}$ and s Chart	199
23. Charts for Multiple Characteristics with Different Targets—The Group Target Charts	207
24. Group Target Individual X and Moving Range Chart	209
25. Group Target $\bar{X}$ and Range Chart	219
26. Group Target $\bar{X}$ and s Chart	229
27. Charts for Short Runs and Multiple Characteristics— The Group Short Run Charts	239
28. Group Short Run Individual X and Moving Range Chart	241
29. Group Short Run $\bar{X}$ and Range [™] Chart	253
30. Group Short Run $\bar{X}$ and s Chart	263
31. Conclusion	273
Appendix: Factors for Variables Data Control Charts	275
Bibliography	281
Index	283