
Contents

Preface	ix	
The Shewhart Catechism	x	
Chapter One	Shewhart's Control Charts	1
1.1	Shewhart's Definition of Statistical Control	2
1.2	Shewhart's "Operation of Statistical Control"	4
1.3	The Four Possibilities for Any Process	6
1.4	Control Charts and the Probability Approach	14
1.5	Enumerative Studies and Analytic Studies	18
1.6	The Uses of Shewhart's Charts	19
1.7	The Four Foundations of Shewhart's Charts	21
1.8	Control Charts and Chaos Theory	25
1.9	The Transformation of Data	28
Chapter Two	Statistics Versus Parameters	31
2.1	Measures of Location and Dispersion	31
2.2	The Notion of a Probability Distribution	33
2.3	Statistics, Parameters, and Control Chart Limits	37
2.4	Skewness and Kurtosis	46
Chapter Three	Estimating Dispersion Parameters	55
3.1	Estimators of $SD(X)$ and $V(X)$ for One Subgroup of Size n	56
3.2	Three Ways to Estimate $SD(X)$ for k Subgroups of Size n	60
3.3	The Second Foundation of Shewhart's Charts	71
3.4	Within-Subgroup Estimates of Dispersion	74
3.5	Time Series Data (Subgroups of Size One)	79
3.6	Degrees of Freedom	80
3.7	Summary	83
Chapter Four	Control Charts for Measurements	85
4.1	Average and Range Charts	88
4.2	Average and Root Mean Square Deviation Charts	92
4.3	Average and Standard Deviation Charts	96
4.4	Average and Variance Charts	103
4.5	So What's the Difference?	106
4.6	Charts for Individual Values	108
4.7	Median and Range Charts	113

Contents

Chapter Five	Three Sigma Limits	115
5.1	Why Three-Sigma Limits?	116
5.2	But What About the Central Limit Theorem?	120
5.3	The Recalculation of Control Limits	122
5.4	The Role of the Normal Distribution	123
5.5	Calculating Limits With Small Amounts of Data	126
5.6	Inadequate Measurement Units	128
5.7	Detecting a Lack of Control	135
5.8	Summary	140
Chapter Six	Rational Sampling and Rational Subgrouping	141
6.1	Rational Sampling	142
6.2	Rational Subgrouping	143
6.3	Principles for Subgrouping	155
6.4	Three-Way Control Charts	157
6.5	Summary	165
Chapter Seven	The Quality of Control Limits	167
7.1	The Distribution of the Average Range Statistic	168
7.2	The Distribution of the Average Root Mean Square Statistic	170
7.3	The Distribution of the Average Standard Deviation Statistic	172
7.4	The Distribution of the Pooled Variance Statistic	174
7.5	The Distribution of the Median Range Statistic	176
7.6	The Distribution of the Average Moving Range	178
7.7	Degrees of Freedom	180
7.8	Effective Degrees of Freedom	182
7.9	Using Degrees of Freedom	183
7.10	The Quality of Control Limits	185
7.11	Summary	186
Chapter Eight	Capability Confusion	187
8.1	Capability, Capability Ratios, and Performance Ratios	188
8.2	The Capability of a Stable Process	188
8.3	Capability Measures	191
8.4	Converting Capabilities Into Fraction Nonconforming	193
8.5	Performance Ratios	196
8.6	World-Class Quality	197
8.7	Summary	203
Chapter Nine	Power Functions for Control Charts	205
9.1	The Power of Charts for Location	206
9.2	The Formulas for the Power Functions	213
9.3	The Average Run Length for a Procedure	223
9.4	Summary	225

Contents

Chapter Ten	Comparing Different Types of Control Charts	225
10.1	Control Charts for Subgroup Averages	227
10.2	Control Charts for Moving Averages	237
10.3	Moving Averages or Individual Values?	239
10.4	<i>Contra</i> Two-Sigma Limits	245
10.5	Summary	250
Chapter Eleven	Control Charts for Count Data	251
11.1	Control Charts for Count Data	252
11.2	<i>np</i> -Charts	255
11.3	<i>p</i> -Charts	256
11.4	A Problem With Binomial Counts	257
11.5	<i>c</i> -Charts	259
11.6	<i>u</i> -Charts	261
11.7	A Problem With Poisson Counts	262
11.8	Degrees of Freedom	267
11.9	Control Charts for Rare Events	267
11.10	Summary	271
Chapter Twelve	Control Charts for Autocorrelated Data	273
12.1	Correlation	273
12.2	Significant Correlations	275
12.3	Autocorrelation	276
12.4	What Does Autocorrelation Say About the Process?	278
12.5	The Effect of Autocorrelation	279
12.6	Autocorrelation's Effect Upon Control Limits	282
12.7	So What Shall I Do With My Autocorrelated Data?	287
Chapter Thirteen	The Cumulative Sum Technique	289
13.1	Cumulative Sums for Individual Values	290
13.2	Cumulative Sums for Subgroup Averages	299
13.3	Average Run Lengths for Selected Cusum Procedures	307
13.4	Summary	311
Chapter Fourteen	Exponentially Weighted Moving Averages	313
14.1	The EWMA Algorithm	313
14.2	EWMA for Individual Values	315
14.3	Average Run Lengths for the EWMA	320
14.4	Then What Does an EWMA Do?	323
14.5	Summary	327

Contents

Chapter Fifteen	Multivariate Charts	329
15.1	Simple Multivariate Control Charts	329
15.2	Control Charts for Hotelling's T^2 Statistic	334
Chapter Sixteen	Miscellaneous Techniques	341
16.1	Zone Charts	341
16.2	Modified Control Charts	346
16.3	PreControl	347
16.4	Summary	354
Chapter Seventeen	The Characterization of Product	355
17.1	Characterizing the Measured Item	356
17.2	Characterizing Product Which Has Not Been Measured	366
17.3	The Fallacy of Acceptance Sampling	368
17.4	Estimating the Fraction Nonconforming	369
17.5	Summary	371
Chapter Eighteen	The Analysis of Means	373
18.1	Comparing k Treatments Using Control Charts	374
18.2	Experimental Data vs. Production Data	375
18.3	The Decision Limits for ANOM	379
18.4	The Role of the Range Chart with ANOM	382
18.5	ANOM With Multifactor Studies	386
18.6	Interaction Effects and ANOM	388
18.7	ANOM With Unequal Subgroup Sizes	390
18.8	The Analysis of Mean Ranges	392
18.9	Summary	397
Chapter Nineteen	Some Differences Between Theory and Practice	399
19.1	The Scientific Process	400
19.2	Statistical Tests of Hypotheses	402
19.3	Enumerative Studies	404
19.4	Analytical Studies	406
19.5	Shewhart on Probability Models and Processes	407
19.6	Finding Decision Rules for Analytic Studies	408
19.7	Conclusions	409

Contents

Appendix		411
Glossary of Symbols		412
Bibliography		414
Tables		416-462
Table 1: Bias Correction Factors		416
Table 2: Bias Correction Factors for Estimating $V(X)$		417
Table 3: Individual Values Charts		418
Table 4: Average and Range Charts Using the Average Range		419
Table 5: Average and Range Charts Using the Median Range		420
Table 6: Average and Range Charts Based on $\Sigma(X)$		421
Table 7: Average and RMS Dev. Charts Using Average RMS Dev.		422
Table 8: Average and RMS Dev. Charts Using Median RMS Dev.		423
Table 9: Average and RMS Dev. Charts Based on $\Sigma(X)$		424
Table 10: Average and Std. Dev. Charts Using Average Std. Dev.		425
Table 11: Average and Std. Dev. Charts Using Median Std. Dev.		426
Table 12: Average and Std. Dev. Charts Based on $\Sigma(X)$		427
Table 13: Average and Std. Dev. Charts Using Pooled Variance		428
Table 14: Median and Range Charts Using the Average Range		430
Table 15: Median and Range Charts Using the Median Range		431
Table 16: Median and Range Charts Based on $\Sigma(X)$		432
Table 17: Average and Variance Charts		433
Table 18: Moments for Range Distributions		434
Table 19: Moments for Distributions of the RMS Deviation		436
Table 20: Moments for Distributions of the Standard Deviation		438
Table 21: Degrees of Freedom for Average Ranges		442
Table 22: Degrees of Freedom for Median Ranges		444
Table 23: Degrees of Freedom for Average Moving Ranges		446
Table 24: Degrees of Freedom for Median Moving Ranges		447
Table 25: Degrees of Freedom for Average Std. Dev. and RMS Dev.		448
Table 26: Degrees of Freedom for Median Std. Dev. and RMS Dev.		450
Table 27: The Standard Normal Distribution		452
Table 28: ANOM Critical Values		454
Table 29: Critical Values for Analysis of Mean Ranges (ANOMR)		458
Table 30: Central Lines and Upper Limits for Hotelling's T^2		462
Table 31: 37 Reference Tables and Figures Located Within Text		463
Index		465