

CONTENTS

Preface

xiii

1

Introduction to Quality Concepts and Statistical Process Control

1

| | | |
|------|---|----|
| 1.1 | What Is Quality? | 1 |
| 1.2 | Definitions of Quality | 3 |
| 1.3 | The Need for SPC | 4 |
| 1.4 | Prevention Versus Detection | 5 |
| 1.5 | SPC Goals | 8 |
| 1.6 | The Basic Tools for SPC | 9 |
| 1.7 | Statistical Process Control Techniques | 9 |
| 1.8 | Applying SPC to an Existing Manufacturing Process | 11 |
| 1.9 | Designed Experiments | 13 |
| 1.10 | The Quality Toolbox | 14 |

2

Striving for Quality: Management's Problem and Management's Solution

17

| | | |
|-----|----------------------|----|
| 2.1 | Management's Problem | 17 |
| 2.2 | Management's Dilemma | 18 |

| | | |
|------|--|----|
| 2.3 | Leadership by Management | 19 |
| 2.4 | Deming's Contribution to Quality | 20 |
| 2.5 | Deming's 14 Points for Management | 22 |
| 2.6 | Deming's Seven Deadly Diseases | 28 |
| 2.7 | Crosby's Approach | 29 |
| | Symptoms of Trouble | 30 |
| | Crosby's Four Absolutes of Quality | 31 |
| | Crosby's 14 Steps to Quality Improvement | 32 |
| 2.8 | A Comparison of Deming's 14 Points and Crosby's 14 Steps | 34 |
| 2.9 | Which Way to Top Quality? | 34 |
| 2.10 | Pitfalls in the Quest for Quality | 36 |
| 2.11 | Total Quality Management (TQM) | 37 |
| 2.12 | The Malcolm Baldrige National Quality Award | 39 |
| 2.13 | Total Customer Satisfaction | 41 |
| 2.14 | ISO-9000 | 43 |
| 2.15 | The Service Sector | 45 |

3

Introduction to Variation and Statistics

47

| | | |
|-----|--|----|
| 3.1 | Measurement Concepts | 47 |
| | Measurement Error | 48 |
| | Round-off Rules | 49 |
| 3.2 | Special-Cause and Common-Cause Variation | 51 |
| 3.3 | The Variation Concepts | 52 |
| 3.4 | Distributions and SPC Goals | 55 |
| 3.5 | Basic Statistical Concepts | 57 |
| | Data Collection | 60 |
| | Data Organization | 61 |
| | Measures of the Center of a Distribution | 61 |
| | Measures of the Spread | 68 |
| 3.6 | Distributions and 3 Standard Deviations | 74 |
| | The Histogram | 77 |

| | | |
|----------|--|------------|
| 4 | Organization of Data: Introduction to Tables, Charts, and Graphs | 83 |
| 4.1 | Stemplots 83 | |
| 4.2 | Frequency Distributions and Tally Charts 87 | |
| 4.3 | Histograms 94 | |
| 4.3 | Histogram Analysis Examples: Shape Interpretation 98 | |
| 4.4 | Pareto Charts 102 | |
| 4.5 | Flowcharts 106 | |
| 4.6 | Storyboards 111 | |
| 4.7 | The Cause-and-Effect Diagram 112 | |
| 4.8 | Checklists 116 | |
| 4.9 | Scatterplots 116 | |
| 5 | Introduction to Probability and the Normal Probability Distribution | 129 |
| 5.1 | Probability 129 | |
| 5.2 | Compound Probability 131 | |
| 5.2 | The "Or" Probability 131 | |
| 5.2 | "And" Probabilities 134 | |
| 5.2 | Adjusting the "And" Rule 136 | |
| 5.3 | Counting with Permutations and Combinations 137 | |
| 5.3 | The Number of Ways 137 | |
| 5.3 | Permutations, $P_{N,n}$ 138 | |
| 5.3 | Factorials 139 | |
| 5.3 | The <i>Mississippi</i> Problem 140 | |
| 5.3 | The Two-Letter Word Problem 141 | |
| 5.3 | Combinations 143 | |
| 5.4 | The Binomial Probability Distribution 145 | |
| 5.4 | The Simple Random Sample 149 | |

| | | |
|-----|--|-----|
| 5.5 | The Hypergeometric Probability Distribution | 149 |
| 5.6 | Probability Distributions | 153 |
| 5.7 | The Normal Probability Distribution | 158 |
| | Area Under a Normal Curve | 162 |
| | Other Normal Curve Tables | 167 |
| 5.8 | The Application of the Central Limit Theorem | 180 |

6 **Introduction to Control Charts** 189

| | | |
|-----|---------------------------------------|-----|
| 6.1 | The Control Chart Concept | 189 |
| | Variables and Attributes | 190 |
| 6.2 | Preparation for Control Charting | 193 |
| | Management Direction | 193 |
| | Planning | 193 |
| | Chart Commentary | 193 |
| | Gauge Capability | 194 |
| | Sampling Plan Preparation | 194 |
| 6.3 | Control Charts and Run Charts | 196 |
| | The Run Chart | 196 |
| 6.4 | The Basic \bar{x} and R Chart | 197 |
| 6.5 | The \bar{x} and R Chart Procedure | 210 |
| | Action Procedures | 216 |
| 6.6 | The Continuation Control Chart | 228 |
| 6.7 | The Capability Analysis | 229 |
| | Calculating the Capability Ratio | 235 |
| | The Capability Index | 236 |
| 6.8 | Six Sigma | 253 |

7 **Additional Control Charts for Variables** 263

| | | |
|-----|---|-----|
| 7.1 | The Median and Range Chart (\tilde{x} and R) | 263 |
| | The \tilde{x} and R Chart Procedure | 263 |
| 7.2 | The \bar{x} and s Chart | 279 |
| 7.3 | Coding Data | 292 |
| 7.4 | A Modified \bar{x} and R Chart for Small Sets of Data | 303 |

| | | |
|-----|--|-----|
| 7.5 | The Nominal \bar{x} and R Chart | 306 |
| 7.6 | The Transformation \bar{x} and R Chart | 311 |
| | The Transformation Formulas | 311 |
| | The Transformation \bar{x} and R Procedure | 312 |
| | Chart Analysis | 315 |
| 7.7 | Control Chart Selection | 316 |

8 Variables Charts for Limited Data 327

| | | |
|-----|---|-----|
| 8.1 | Precontrol or Rainbow Charts | 328 |
| | The Precontrol Procedure | 328 |
| | Calculating Zones | 329 |
| 8.2 | A Compound Probability Application | 332 |
| 8.3 | Modified Precontrol for Tight Control | 333 |
| 8.4 | Charts for Individual Measurements | 339 |
| | The Run Chart | 339 |
| | The x and MR Chart | 340 |
| | Procedure for the Individual and Moving Range Chart | 341 |

9 Attributes Control Charts 361

| | | |
|-----|-------------------------------------|-----|
| 9.1 | The Four Types of Attributes Charts | 362 |
| | The p Chart | 362 |
| | The np Chart | 362 |
| | The c Chart | 362 |
| | The u Chart | 362 |
| | Applications of the Charts | 362 |
| 9.2 | The p Chart | 363 |
| | Preparation for the p Chart | 363 |
| | The p Chart Procedure | 364 |
| 9.3 | The np Chart | 374 |
| 9.4 | The c Chart | 379 |
| 9.5 | The u Chart | 383 |
| 9.6 | SPC Applied to the Learning Process | 387 |
| 9.7 | Technology in SPC | 390 |

| | | |
|-----------|--|------------|
| 10 | Interpreting Control Charts | 397 |
| 10.1 | The Random Distribution of Points | 399 |
| 10.2 | Freaks | 400 |
| 10.3 | Binomial Distribution Applications | 403 |
| 10.4 | Freak Patterns | 408 |
| 10.5 | Shifts | 413 |
| 10.6 | Runs and Trends | 418 |
| 10.7 | Time and Control Chart Patterns | 422 |
| 10.8 | Cycles | 423 |
| 10.9 | Grouping | 425 |
| 10.10 | Instability | 428 |
| 10.11 | Stable Mixtures | 429 |
| 10.12 | Stratification | 430 |
| 10.13 | Using Control Chart Patterns in Problem Solving | 436 |
| 11 | Problem Solving | 443 |
| 11.1 | The Problem-Solving Sequence | 443 |
| 11.2 | Teamwork for Problem Solving | 445 |
| 11.3 | Brainstorming | 448 |
| 11.4 | Using Problem-Solving Tools | 450 |
| | Histograms for Problem Solving | 451 |
| | Verifying Vendor Quality | 460 |
| 11.5 | Mistake Proofing | 474 |
| 11.6 | Problem Solving in Management | 476 |
| 11.7 | JIT (Just-in-Time) | 479 |
| 11.8 | Problem Solving in the Classroom | 480 |
| 12 | Gauge Capability | 485 |
| 12.1 | Preparations for a Gauge Capability Study | 487 |
| 12.2 | The Gauge Capability Procedure | 487 |
| 12.3 | Analysis of R and R with Accuracy and Stability: Maximum Possible Deflection | 501 |

| | | |
|------|---|-----|
| 12.4 | The Elimination of Gauge Variation from Process Variation | 506 |
| 12.5 | Indecisive Gauge Readings | 509 |

13 Acceptance Sampling 513

| | | |
|------|---|-----|
| 13.1 | The Sampling Dilemma | 514 |
| 13.2 | Random Sampling | 521 |
| 13.3 | Operating Characteristic Curves | 522 |
| | Selecting the Best OC Curve | 532 |
| | Selecting the AQL | 533 |
| 13.4 | The Average Outgoing Quality Curve | 534 |
| 13.5 | MLT-STD-105D for Inspection by Attributes | 537 |
| 13.6 | The Average Proportion Defective | 550 |
| 13.7 | Vendor Certification and Control Chart Monitoring | 555 |

A Basic Math Concepts and Probability 557

| | | |
|-----|----------------------------------|-----|
| A.1 | Signed Numbers | 557 |
| | Operations with Signed Numbers | 558 |
| | Addition Rules | 558 |
| | Subtraction | 560 |
| | Multiplication and Division | 561 |
| A.2 | Variables | 562 |
| | Operations | 563 |
| | Addition | 563 |
| | Subtraction | 563 |
| | Multiplication | 564 |
| | Division | 564 |
| | Powers | 564 |
| | Roots | 566 |
| A.3 | Order of Operations | 567 |
| A.4 | Inequalities | 569 |
| A.5 | Using the Statistical Calculator | 571 |

| | |
|-----------------------------|---|
| B | |
| Charts and Tables | 573 |
| B.1 | Formulas and Constants for Control Charts 573 |
| | Average and Range Charts: \bar{x} and R 573 |
| | Median and Range Charts: \tilde{x} and R 574 |
| | Average and Standard Deviation: \bar{x} and s 575 |
| | Individual Measurement and Moving Range: x and MR 575 |
| | Attributes Charts 576 |
| B.2 | The G Chart 579 |
| B.3 | The Normal Distribution Table (Tail Area) 580 |
| B.4 | The Normal Distribution Table (Center Area) 582 |
| B.5 | The Normal Distribution Table (Left Area) 584 |
| B.6 | Process Capability 586 |
| C | |
| Glossary of Symbols | 587 |
| D | |
| Lab Exercises | 589 |
| Answers to Exercises | 605 |
| Index | 647 |