

Contents

Preface	xi
1 Introduction to the T^2 Statistic	1
1.1 Introduction	3
1.2 Univariate Control Procedures	4
1.3 Multivariate Control Procedures	5
1.4 Characteristics of a Multivariate Control Procedure	9
1.5 Summary	11
2 Basic Concepts about the T^2 Statistic	13
2.1 Introduction	13
2.2 Statistical Distance	13
2.3 T^2 and Multivariate Normality	17
2.4 Student t versus Hotelling's T^2	20
2.5 Distributional Properties of the T^2	22
2.6 Alternative Covariance Estimators	26
2.7 Summary	28
2.8 Appendix: Matrix Algebra Review	28
2.8.1 Vector and Matrix Notation	29
2.8.2 Data Matrix	29
2.8.3 The Inverse Matrix	30
2.8.4 Symmetric Matrix	30
2.8.5 Quadratic Form	31
2.8.6 Wishart Distribution	32
3 Checking Assumptions for Using a T^2 Statistic	33
3.1 Introduction	33
3.2 Assessing the Distribution of the T^2	33
3.3 The T^2 and Nonnormal Distributions	37
3.4 The Sampling Distribution of the T^2 Statistic	37
3.5 Validation of the T^2 Distribution	41
3.6 Transforming Observations to Normality	47
3.7 Distribution-Free Procedures	48
3.8 Choice of Sample Size	49

3.9	Discrete Variables	50
3.10	Summary	50
3.11	Appendix: Confidence Intervals for UCL	51
4	Construction of Historical Data Set	53
4.1	Introduction	54
4.2	Planning	55
4.3	Preliminary Data	57
4.4	Data Collection Procedures	61
4.5	Missing Data	62
4.6	Functional Form of Variables	64
4.7	Detecting Collinearities	65
4.8	Detecting Autocorrelation	68
4.9	Example of Autocorrelation Detection Techniques	72
4.10	Summary	78
4.11	Appendix	78
	4.11.1 Eigenvalues and Eigenvectors	78
	4.11.2 Principal Component Analysis	79
5	Charting the T^2 Statistic in Phase I	81
5.1	Introduction	81
5.2	The Outlier Problem	81
5.3	Univariate Outlier Detection	82
5.4	Multivariate Outlier Detection	85
5.5	Purging Outliers: Unknown Parameter Case	86
	5.5.1 Temperature Example	86
	5.5.2 Transformer Example	89
5.6	Purging Outliers: Known Parameter Case	91
5.7	Unknown T^2 Distribution	92
5.8	Summary	96
6	Charting the T^2 Statistic in Phase II	97
6.1	Introduction	98
6.2	Choice of False Alarm Rate	98
6.3	T^2 Charts with Unknown Parameters	100
6.4	T^2 Charts with Known Parameters	105
6.5	T^2 Charts with Subgroup Means	106
6.6	Interpretive Features of T^2 Charting	108
6.7	Average Run Length (Optional)	111
6.8	Plotting in Principal Component Space (Optional)	115
6.9	Summary	118
7	Interpretation of T^2 Signals for Two Variables	119
7.1	Introduction	119
7.2	Orthogonal Decompositions	120
7.3	The MYT Decomposition	125

7.4	Interpretation of a Signal on a T^2 Component	127
7.5	Regression Perspective	129
7.6	Distribution of the T^2 Components	131
7.7	Data Example	135
7.8	Conditional Probability Functions (Optional)	140
7.9	Summary	142
7.10	Appendix: Principal Component Form of T^2	143
8	Interpretation of T^2 Signals for the General Case	147
8.1	Introduction	147
8.2	The MYT Decomposition	147
8.3	Computing the Decomposition Terms	149
8.4	Properties of the MYT Decomposition	152
8.5	Locating Signaling Variables	155
8.6	Interpretation of a Signal on a T^2 Component	157
8.7	Regression Perspective	162
8.8	Computational Scheme (Optional)	163
8.9	Case Study	165
8.10	Summary	169
9	Improving the Sensitivity of the T^2 Statistic	171
9.1	Introduction	172
9.2	Alternative Forms of Conditional Terms	172
9.3	Improving Sensitivity to Abrupt Process Changes	174
9.4	Case Study: Steam Turbine	175
9.4.1	The Control Procedure	175
9.4.2	Historical Data Set	176
9.5	Model Creation Using Expert Knowledge	180
9.6	Model Creation Using Data Exploration	183
9.7	Improving Sensitivity to Gradual Process Shifts	188
9.8	Summary	191
10	Autocorrelation in T^2 Control Charts	193
10.1	Introduction	193
10.2	Autocorrelation Patterns in T^2 Charts	194
10.3	Control Procedure for Uniform Decay	199
10.4	Example of a Uniform Decay Process	201
10.4.1	Detection of Autocorrelation	202
10.4.2	Autoregressive Functions	202
10.4.3	Estimates	207
10.4.4	Examination of New Observations	209
10.5	Control Procedure for Stage Decay Processes	211
10.6	Summary	212
11	The T^2 Statistic and Batch Processes	213
11.1	Introduction	213

11.2	Types of Batch Processes	213
11.3	Estimation in Batch Processes	217
11.4	Outlier Removal for Category 1 Batch Processes	219
11.5	Example: Category 1 Batch Process	221
11.6	Outlier Removal for Category 2 Batch Processes	226
11.7	Example: Category 2 Batch Process	226
11.8	Phase II Operation with Batch Processes	230
11.9	Example of Phase II Operation	232
11.10	Summary	234
Appendix. Distribution Tables		237
Bibliography		253
Index		259