

Contents

<i>Preface</i>	xi
1. Introduction	1
The Importance of Manufacturing.....	1
Manufacturing and Wealth: A Historical Lesson.....	3
The Importance of Quality.....	5
What Is Quality?.....	7
What Are Specifications?.....	9
Who Are Customers?.....	12
The Manufacturing Worker's Role in Quality.....	13
Self-Directed Work Teams.....	14
Customer Contact Teams.....	16
Quality Improvement Teams.....	18
2. Tools for Improving Productivity and Quality	21
Friction.....	21
Total Productive Maintenance and Preventive Maintenance.....	24
5S-CANDO.....	31
Improving Productivity: Synchronous Flow Manufacturing.....	33
Check Sheets.....	39
Histograms.....	41
Pareto Charts.....	42
Histograms—Continued.....	43
Process Flowcharts.....	46
Critical Processes.....	48
Cost of Quality.....	50
Cause-and-Effect (Fishbone) Diagrams.....	52
Case Study: Wafer Breakage.....	54
Team-Oriented Problem Solving: Eight Disciplines.....	59
"Is/Is Not" Analysis.....	62

ISO 9000.....	64
Documentation Control.....	64
Product Identification and Traceability.....	65
Process Control	66
Inspection, Testing, Calibration, and Control	66
Control of Nonconforming Product	67
Storage, Packaging, Handling, and Delivery.....	68
Other Provisions	69
Major Problem Areas.....	70
Problems	70
Solutions	73
 3. Statistical Process Control.....	 77
Variation and Accuracy.....	77
Process Capability and Tight Specifications	80
Quantity Versus (?) Quality.....	83
Accuracy.....	85
Overadjustment or Tampering	86
Random Variation and Assignable Causes	87
The Normal Distribution	88
The Normality Assumption	92
Feedback Process Control.....	93
Requirements for Successful SPC	97
Statistics.....	99
Average.....	99
Range	100
Standard Deviation.....	100
Outliers	103
Control Charts.....	106
Risks.....	106
Taking the Sample.....	108
Plotting the Data on a Chart	111
Interpreting the Chart.....	116
Special Patterns	120
Problems.....	122
Solutions	126

4. Attribute Control Charts	127
Traditional Attribute Control Charts.....	131
np and p Charts.....	131
c and u Charts	133
Points Below the Lower Control Limit	134
Normal Approximation (Assumption)	136
Multiple Attribute Control Charts	137
Technical Appendix: Multiple Attribute Charts.....	141
Hypergeometric Distribution	141
Binomial Distribution	143
Poisson (Defect or Random Arrival) Situation.....	147
Normal Approximation: Binomial and Poisson Distributions....	148
5. Other Topics	149
Gage Capability.....	149
Elements of Gage Variation	151
Inspection Capability.....	154
Improvements in Inspection.....	155
Designing and Building in Quality	156
Nested Sources of Variation.....	158
Multivariate Systems	162
Technical Appendix: Variance Components	163
Variance Components for Batch Processes	163
Gage Studies	168
Gage Capability and Process Capability	173
Gage Capability and Outgoing Quality.....	175
6. Process Characterization and Advanced Techniques	177
The Normal Distribution	177
Cumulative Normal Distribution.....	178
Tests for Normality	183
Chi Square Test for Goodness of Fit	184
The Normal Probability Plot.....	191
Central Limit Theorem	195
Setting up a Control Chart.....	196
Theoretical Control Charts	197
Empirical Control Charts	197
Empirical Chart for Individuals ($\bar{X}$ Charts).....	201

Process Capability Indices.....	203
Uncertainty in Capability Indices.....	206
Special Control Charts.....	207
z Charts.....	207
Center Band Charts (Acceptance Control Charts).....	211
CUSUM and EWMA (Awareness).....	214
False Alarm Risks and Power of Shewhart Control Charts	214
Appendices.....	219
A Percentiles of the Standard Normal Distribution.....	219
B Percentiles of the Chi Square Distribution	223
C Percentiles of the Student's t Distribution	227
D F Distribution Tables.....	231
E Control Chart Formulas and Control Chart Factors	239
F Statistical Functions for Spreadsheets and Random Number Generation for In-House Training.....	243
G Confidence Limits for Capability Indices CPL and CPU	247
H Useful World Wide Web Resources.....	249
<i>Bibliography</i>	251
<i>Index</i>	255