

## Contents

**Preface** XIII

**List of Symbols** XVII

<b>0</b>	<b>Introduction</b>	1
0.1	General Differentiation of Analytical Processes	3
0.2	Quality of Analytical Processes and Results	4
0.3	The System of Analytical Quality Assurance	4
0.4	The Four-Phase Model of Analytical Quality Assurance	6
<b>1</b>	<b>Phase I: Establishing a New Analytical Procedure</b>	9
1.1	Introduction	9
1.1.1	Objectives of Phase I	9
1.1.2	When Are Characteristic Data Obtained?	9
1.1.3	The Progression of Phase I	10
1.1.4	Results of Phase I; Statistical Data	14
1.2	Calibration of the Fundamental Analytical Procedure	15
1.2.1	Establishment of an Analytical Range	16
1.2.2	Preparation of Standard Samples	16
1.2.3	Determination of the Calibration Function and Process Data	17
1.2.3.1	Process Data for the Linear Calibration Function	18
1.2.3.2	Process Data for the Second-Order Calibration Function	19
1.2.3.3	Calculating Analytical Results with the Aid of the Calibration Function	21
1.2.4	Verification of the Fundamental Calibration	23
1.2.4.1	Verification of Linearity	23
1.2.4.2	Verification of Precision	25
1.3	Analyses at Very Low Concentrations	29
1.3.1	Decision Limit	32
1.3.2	Determining the Minimum Detectable Value	34
1.3.2.1	Minimum Detectable Value, Determined Using the Distribution of Blank Values	34

1.3.2.2	Minimum Detectable Value, Obtained Using the Calibration Function	35
1.3.3	Limit of Quantification	35
1.3.4	Quick Estimation	36
1.3.5	Estimation of the Decision Limit and Limit of Quantification Using the <i>S/N</i> Ratio	37
1.4	Validation of Individual Process Steps and Examination of Matrix Influences	37
1.4.1	Systematic Errors	37
1.4.1.1	Constant Systematic Errors, Additive Deviations	37
1.4.1.2	Proportional Systematic Errors, Multiplicative Deviations	38
1.4.2	Establishment and Assessment of the Recovery Function	38
1.4.2.1	Prerequisites for the Interpretation of the Recovery Function	39
1.4.2.2	Testing for Systematic Errors	40
1.4.3	Application of the Recovery Function	41
1.4.3.1	Checking Individual Process Steps	41
1.4.3.2	Determination of the Recovery Function to Prove the Influence of a Matrix	45
1.5	Additional Statistical Methods	46
1.6	Use of Internal Standards	46
1.6.1	Definition, Purpose	46
1.6.2	Conditions and Limitations of the Use of Internal Standards	47
1.6.3	Procedure	47
1.7	Preparing for Routine Analysis	49
1.7.1	Examination of the Time Dependency of Measured Values	49
1.7.1.1	Comparison of the "Within Batch" Standard Deviation ( $s_w$ ) with the "Between Batches" Standard Deviation ( $s_b$ )	49
1.7.1.2	Determining the Need for Daily Adjustment of Analytical Equipment	51
1.7.1.3	The Trend Test	51
1.8	Summary of the Results of Phase I (Process Development): Documentation	54
<b>2</b>	<b>Phase II: An Analytical Process Becomes Routine; Preparative Quality Assurance</b>	<b>57</b>
2.1	Introduction	57
2.1.1	Objectives of Phase II	57
2.1.2	Execution of Phase II	57
2.1.3	Progression of Phase II	57
2.1.4	Results of Phase II	58
2.2	Selection of the Analytical Procedure	59
2.2.1	Specificity of the Procedure	60
2.2.2	Selectivity of the Analytical Procedure	60
2.2.3	Working Range	60
2.2.4	Calibration Function, Sensitivity, and Precision of the Procedure	60

2.2.5	Minimum Detectable Value and Limit of Quantification	61
2.2.6	Risk of Systematic Error	61
2.2.7	Effort, Costs	61
2.3	The “Training” Phase of the Process	62
2.4	Establishment of Quality Objectives to be Adhered to in Routine Usage	64
2.4.1	External Quality Requirements	65
2.4.2	Internal Quality Requirements	66
2.5	Control Samples for Internal Quality Assurance	66
2.5.1	Requirements of Control Samples	66
2.5.2	Types of Control Samples	67
2.5.2.1	Standard Solutions	67
2.5.2.2	Blank Samples	67
2.5.2.3	Natural Samples	67
2.5.2.4	Spiked Natural Samples	68
2.5.2.5	Synthetic Samples	68
2.5.2.6	Certified Reference Materials (CRMs)	68
2.5.3	Requirements for Producers of Control Materials	69
2.5.4	Applicability of Control Sample Types	69
2.6	The Control Chart System	70
2.6.1	Introduction: History of the Control Chart	70
2.6.2	Principle of a Control Chart	72
2.6.3	Average Run Length (ARL) and Evaluation of Control Charts	73
2.6.4	Derivation of the Average Run Length (ARL)	74
2.6.4.1	Examples of Theoretical Calculations	75
2.6.4.2	Analytical Example	76
2.6.5	Concept for the Preparation of Routine Quality Control	78
2.6.6	Evaluation of the Preliminary Period	80
2.6.6.1	Variance Analysis	80
2.6.6.2	Adherence to Required Quality Objectives	80
2.6.7	Types of Control Charts and Their Applications	80
2.6.7.1	Shewhart Charts	81
2.6.7.2	R-Chart (Range Control Chart)	89
2.6.7.3	Difference Chart	96
2.6.7.4	Standard Deviation Chart (s-Chart)	98
2.6.7.5	Target Value Charts	99
2.6.7.6	Cusum Chart	100
2.6.8	Summary of the Characterization of Control Charts	112
<b>3</b>	<b>Phase III: Routine Quality Assurance</b>	<b>115</b>
3.1	Introduction	115
3.1.1	Setting the Objectives of Phase III	115
3.1.2	Execution of Phase III	115
3.1.3	Progression of Phase III	115
3.2	Fundamental Measures of Internal Quality Assurance	118

3.2.1	The Laboratory and Laboratory Management	118
3.2.2	Personnel	119
3.2.3	Outfitting and Equipment	119
3.2.3.1	Performance Monitoring, Calibration and Adjustment of Measuring Equipment	119
3.2.3.2	Maintenance of Equipment	120
3.2.4	Materials	121
3.2.4.1	Certifying Sample Quality	121
3.2.4.2	Analysis-Related Materials	121
3.2.4.3	Control Samples for Routine Quality Control	122
3.2.5	Instituted Analytical Processes	122
3.2.6	Testing the Equivalency of Analytical Results	122
3.2.6.1	Testing the Equivalency for a Single Matrix	123
3.2.6.2	Testing the Equivalency in Different Matrices	126
3.2.7	Uncertainty of Measurements	130
3.2.7.1	New Terms According to the EURACHEM Guide	131
3.2.7.2	Overview of Common Procedures for the Determination of Measurement Uncertainty	133
3.2.7.3	Indication of Measurement Uncertainty in Test Reports	142
3.2.7.4	Interpretation of Measurement Uncertainty in the Context of Limit Value Monitoring	143
3.2.7.5	Summary	144
3.2.8	Reporting Analytical Results	145
3.3	Routine Quality Control	145
3.3.1	Trueness Control	146
3.3.1.1	General	146
3.3.1.2	Blank Value Monitoring	146
3.3.1.3	$\bar{x}$ -Chart	148
3.3.1.4	Recovery Rate Control Chart	148
3.3.2	Precision Control	148
3.3.2.1	General	148
3.3.2.2	Precision Control Using an <i>R</i> -Chart	149
3.3.2.3	Securing Precision Using a Standard Deviation Control Chart	149
3.3.3	Revision of Quality Control Charts	150
3.3.4	Quality Assurance in the Case of Time-Consuming or Infrequent Analyses	150
3.4	Special Quality Problems in Routine Analysis	151
3.4.1	Matrix Effects	151
3.5	Corrective Measures	154
3.5.1	Sources of Error in Analytical Laboratories	154
3.5.2	Systematic Troubleshooting	155
3.5.2.1	Analytical Errors That Can Be Detected Using Statistical Quality Control Methods	161
3.5.2.2	Plausibility Checks	162
3.6	Documentation and Archiving	166

<b>4</b>	<b>Phase IV: External Analytical Quality Assurance</b>	169
4.1	Introduction	169
4.2	Audits	169
4.3	Interlaboratory (or Round Robin) Tests	170
4.3.1	Interlaboratory Tests for Process Standardization	171
4.3.2	Interlaboratory Tests as Proof of Laboratory Performance	171
4.3.3	Other Interlaboratory Tests	172
4.3.4	Planning and Execution of Interlaboratory (or Round Robin) Tests	173
4.3.4.1	Quality Management System of the Provider of an Interlaboratory Test	173
4.3.4.2	Planning the Interlaboratory Test	174
4.3.4.3	Interlaboratory Test Samples	175
4.3.5	Procedures for the Execution and Evaluation of Interlaboratory Tests	176
4.3.5.1	Interlaboratory Test Programs According to ISO 5725-2	177
4.3.5.2	The Youden Method of Interlaboratory Tests	179
4.3.5.3	Interlaboratory Tests According to ISO Guide 43	188
4.4	Effects of Internal Quality Assurance on the Results of Interlaboratory Tests	191
4.5	Conclusion	194
<b>5</b>	<b>Definitions</b>	195
5.1	Quality and Quality Management	195
5.2	Analytical Terms	197
5.3	Analytical Results	201
5.4	Deviation, Uncertainty	202
5.5	Materials, Samples	205
5.6	Statistical Tests	206
<b>6</b>	<b>References</b>	

## Appendix 1

A1	Sample Calculations	219
A1.1	Fundamental Calibration	219
A1.2	Linearity Tests	221
A1.2.1	Visual Linearity Test	221
A1.2.2	Second-Order Calibration Function	222
A1.2.3	Linearity Test: Goodness-of-Fit Test	224
A1.2.4	Variance Homogeneity Test	226
A1.2.5	Outlier Tests for Linear Calibration	228
A1.2.6	Securing the Lower Range Limit	230
A1.2.7	Decision Limit, Minimum Detectable Value, and Limit of Quantification	231
A1.2.8	Recovery Function	236

A1.2.9	Testing Analytical Results for Temporal Stability	239
A1.2.10	Trend Test	242
A1.2.11	Practice Phase: Checking the Analysis Quality Achieved Based on the Process Standard Deviation	243
A1.3	Phases II and III: Control Charts	244
A1.3.1	Blank Value Control Chart	245
A1.3.2	$\bar{x}$ -Chart for Standard Solutions	246
A1.3.3	Recovery Rate (RR) Control Chart	247
A1.3.4	Verifying Precision by Means of R-Charts and s-Charts	249
A1.3.5	Testing for Series-Internal Drift	251
A1.3.6	RR-Control Chart by Addition of a Standard	253
A1.3.7	Cusum Chart	254
A1.3.8	Equivalency	258
A1.3.9	Standard Addition	261

**Appendix 2**

A2	Statistical Tables	263
A2.1	<i>t</i> -Table	263
A2.2	<i>F</i> -Table (95 %)	264
A2.2	<i>F</i> -Table (99 %)	265
A2.3	Grubbs Table	267
A2.4	$\chi^2$ -Table	268

**Appendix 3**

A3	Contents of the CD	269
A3.1	Checklists	269
A3.2	Instructions for Using the Calculation Examples	269
A3.3	Statistical Table Values	270

**Subject Index** 271