

Contents

1	Introduction	1
1.1	The Notion Material	1
1.2	The Notion Metal	2
1.3	Models and Experiments	3
1.4	Bridging Length Scales	4
1.5	Understanding of Nature, the Role of Science: Magic, Discovery and Models	5
2	Electronic Structure of the Atom; the Periodic Table	9
2.1	Protons, Neutrons and Electrons	9
2.2	Rutherford's Model (1911)	9
2.3	Bohr's Model (1913)	9
2.4	The Wave or Quantum-Mechanical Model (Heisenberg/Schrödinger, 1926); Quantum Numbers	12
	<i>Intermezzo: A "Derivation" of the Uncertainty Relation; Diffraction of Moving Particles at a Slit</i>	14
2.4.1	The Probability Amplitude	16
2.4.2	Characterizing the Possible Energy States; the Quantum Numbers	17
2.5	The Pauli Exclusion Principle and the "Aufbau Prinzip"	20
	<i>Intermezzo: The Discoverers of the Periodic System; A First Example of a "Priority Battle"</i>	26
	<i>Epilogue: The Extent of the Periodic Table</i>	27
2.5.1	Atom Size and Ionization Energy	28
2.6	The Shape of the Probability Density Distribution for the Electron	31
	References	36
3	Chemical Bonding in Solids; with Excursions to Material Properties	37
3.1	Attractive and Repulsive Forces; Thermal Expansion and Elastic Constants	37
	<i>Intermezzo: The Linear Coefficient of Thermal Expansion of Large and Small Crystals</i>	40
3.2	Remarks on Model Types of Bonding	43
3.3	Ionic Bonding; Lattice Energy and the Madelung Factor	44
3.4	Covalent Bonding	51
3.5	Metal Bonding	57

3.5.1	The Free Electron Models	57
3.5.2	Zone or Band Models	67
3.5.3	The Crystal Structure of Metals	82
3.6	van der Waals Bonding	91
3.7	Hydrogen Bonding	94
	<i>Epilogue: "How Science Really Happens"</i>	99
	References	100
4	Crystallography	103
	<i>Intermezzo: Making Grain Boundaries Visible</i>	106
4.1	Geometric Description of Crystals	107
4.1.1	Translation Lattice, Motif and Crystal Structure	107
4.1.2	The Crystal System	115
	<i>Intermezzo: A Short Note on Point Groups, Crystallographic</i> <i>Point Groups, Plane Groups and Space Groups;</i> <i>Glide and Screw Operations</i>	118
4.1.3	The Bravais Categorization of Translation Lattices	120
4.1.4	Description of Lattice Planes and Directions; Miller and Miller–Bravais Indices	123
4.2	Crystal Structures of Elements	129
4.2.1	Crystal Structures Derived from Close Packed Arrangements of Hard Spheres	130
4.2.2	The Body Centred Cubic (b.c.c.) Crystal Structure	141
4.2.3	Further Crystal Structures of Elements	145
4.2.4	The Coordination Number	149
4.2.5	Polymorphism and Allotropy	150
4.3	The Notions Alloy, Solid Solution, Ordered Solid Solution and Compound	152
4.4	Crystalline Solid Solutions and Compounds	153
4.4.1	Substitutional Solid Solutions	153
4.4.2	Interstitial Solid Solutions	159
	<i>Intermezzo: Thermochemical Surface Engineering;</i> <i>Nitriding and Carburizing of Iron and Steels</i>	168
4.4.3	Crystal Structures of Further Materials	170
4.5	Determination of the Crystal Structure; X-Ray Diffraction Analysis	171
	<i>Intermezzo: The von Laue Theory</i>	173
4.6	The Stereographic Projection	178
4.7	The Texture of a Polycrystal; the Pole Figure, the Inverse Pole Figure and the Orientation Distribution Function	180
4.8	Aperiodic Crystals	189
4.8.1	Incommensurately Modulated Atomic Structures	189
4.8.2	Quasicrystals	193
	<i>Intermezzo: A Revolution in Crystallography; "Young" Versus "Old"</i>	193
	<i>Epilogue: The Notion Crystal Revisited</i>	197
	Appendix: How to Deal with Atoms at Unit-Cell Boundaries	198
	References	200

5	The Crystal Imperfection; Lattice Defects	201
5.1	Point Defects (Zero-Dimensional): Thermal and Constitutional Vacancies; Interstitial, Substitutional and Antistructure Atoms; Schottky and Frenkel Defects	202
5.2	Line Defects (One-Dimensional): Edge and Screw Dislocations	206
5.2.1	The Edge Dislocation	207
5.2.2	The Screw Dislocation	208
5.2.3	Dislocation Line and Burgers Vector; Dislocation Density	209
	<i>Intermezzo: A Historical Note About the Burgers Vector</i>	211
5.2.4	Strain Energy of a Dislocation	213
5.2.5	Glide of Dislocations; Slip Systems	215
	<i>Intermezzo: The Peierls Stress</i>	217
5.2.6	Dislocation Production: Frank–Read Source, Cross-Slip and Vacancy Condensation	219
5.2.7	Climb of Dislocations	223
5.2.8	Partial and Sessile Dislocations	224
5.3	Planar Defects (Two-Dimensional): Grain Boundaries, Twin Boundaries, Stacking Faults and Antiphase Boundaries; Coherent and Incoherent Interfaces	228
	<i>Intermezzo: Coherent and Incoherent Interfaces Versus Coherent and Incoherent Diffraction</i>	240
5.4	Volume Defects (Three-Dimensional): Second-Phase Particles and Pores	241
	References	243
6	Analysis of the Microstructure; Analysis of Lattice Imperfections: Light and Electron Microscopical and X-Ray Diffraction Methods	245
6.1	The Lens	246
6.1.1	The Paraxial Approximation	246
6.1.2	The Compound Lens	249
6.2	Image Formation	249
6.3	The (Reflected) Light Optical Microscope	253
6.3.1	The Magnifier (“Loupe”)	253
6.3.2	The Compound Microscope	255
6.4	Köhler Illumination	257
6.5	Resolving Power	259
6.5.1	Minimal Image Construction	259
6.5.2	Maximal Magnification	260
6.6	Bright and Dark Field and Other Imaging Techniques by Light Microscopy	261
6.7	Transmission Electron Microscopy	267
6.7.1	Basic Constitution and Action of the TEM: Imaging and Diffraction Modes	269
6.7.2	The Diffraction Pattern; the Zone Law	271

6.7.3	Diffraction Contrast Images: Bright Field and Dark Field “Imaging”	272
6.7.4	Examples of Bright and Dark Field TEM Images	274
6.7.5	Convergent Beam Electron Diffraction (CBED); Microdiffraction; Scanning Transmission Electron Microscopy (STEM)	276
6.7.6	High-Resolution Transmission Electron Microscopy (HRTEM)	280
6.7.7	Analytical Electron Microscopy (AEM); Chemical Composition Maps; Electron Probe Micro-Analysis (EPMA) and Electron Energy Loss Spectroscopy (EELS)	283
6.8	Scanning Electron Microscopy	285
6.8.1	Secondary Electron Images	287
6.8.2	Back-Scattered Electron Images	288
6.8.3	Chemical Composition Maps; Electron Probe Micro-Analysis (EPMA)	288
6.9	X-ray Diffraction Analysis of the Imperfect Microstructure	290
6.9.1	Determination of Crystallite Size and Microstrain	291
6.9.2	Determination of (Residual) Macrostress	296
	<i>Intermezzo: Grain Interaction</i>	299
	<i>Intermezzo: Surface Anisotropy and Thin Films</i>	300
	References	301
7	Phase Equilibria	303
7.1	The Notion Phase	304
7.2	The Notion Component	304
7.3	The Notions Equilibrium and Stationary State: Internal Energy, Entropy, (Helmholtz) Free Energy and Gibbs Energy	305
7.4	Degrees of Freedom; the Phase Rule	310
7.5	Phase Diagrams	311
7.5.1	One-Component Systems	311
	<i>Intermezzo: Entropy of Fusion and the Structure of Liquids</i>	313
7.5.2	Binary Systems	314
7.5.3	Ternary Systems	330
7.6	Microstructure Development with Reference to the Phase Diagram	334
	References	337
8	Diffusion	339
8.1	The Continuum Approach to Diffusion; Fick’s First and Second Laws	339
8.2	The Atomistic Approach to Diffusion	342
	<i>Intermezzo: Brownian motion</i>	343
8.3	Solutions of Fick’s Laws	345
8.4	Diffusion Mechanisms in Crystalline Systems	347
8.4.1	Exchange Mechanisms	347

8.4.2	The Vacancy Mechanism; Substitutional Diffusion . . .	348
8.4.3	Interstitial Diffusion	348
8.5	The Jump Frequency and the Activation Energy of Diffusion . .	349
8.5.1	The Determination of ΔH_{vac}	354
8.5.2	The Determination of ΔH_{mig}	356
8.6	Microstructure and Diffusion	357
8.6.1	Diffusion Along the Low-Angle Symmetrical Tilt Boundary	359
8.6.2	Diffusion Along a Moving Grain Boundary	360
	<i>Intermezzo: Priority and Scientific Decency</i>	362
	Appendix: Diffusion in Thin Film Systems; Concentration–Depth Profiles	365
	References	368
9	Phase Transformations	371
9.1	Thermodynamics and Kinetics of Phase Transformations; Thermal Activation and the Activation Energy	372
9.2	Energetics of Nucleation; Homogeneous and Heterogeneous Transformations; Homogeneous and Heterogeneous Nucleation	374
	<i>Intermezzo: Nucleation of AlN in Fe–Al Alloy</i>	377
9.3	Diffusional and Diffusionless Transformations	378
9.4	Diffusional Transformations; Examples	380
9.4.1	Age-Hardening Alloys; “Clusters”, Transition and Equilibrium Precipitates	380
9.4.2	Eutectoid Transformation	385
	<i>Intermezzo: The Fe–C System; Steels and Cast Irons</i>	386
9.4.3	Discontinuous Transformation	391
9.4.4	The Widmanstätten Morphology	394
9.4.5	Grain-Boundary Wetting	395
9.5	Diffusionless Transformations; Examples	399
9.5.1	The Massive Transformation	400
9.5.2	The Martensitic Transformation	404
	<i>Intermezzo: Shape Memory Alloys</i>	418
	<i>Intermezzo: The Hardness of Iron-Based Interstitial Martensitic Specimens</i>	420
	<i>Intermezzo: Tempering of Iron-Based Interstitial Martensitic Specimens</i>	421
9.6	The Analysis of the Kinetics of Phase Transformations	424
9.6.1	Time–Temperature–Transformation (TTT) Diagrams and Continuous Cooling Transformation (CCT) Diagrams	426
9.6.2	Thermal History and the Stage of Transformation	429
9.6.3	The Transformation Rate; the Additivity Rule	432
9.6.4	Heterogeneous Phase Transformations as a Composite Phenomenon: Nucleation, Growth and Impingement	432
9.6.5	Modes of Nucleation	433
9.6.6	Modes of Growth	436

9.6.7	The Activation Energies for Nucleation and Growth	438
9.6.8	Extended Volume and Extended Transformed Fraction	439
9.6.9	Modes of Impingement	442
9.6.10	The Transformed Fraction	444
9.6.11	The Classical and Generalized Johnson–Mehl–Avrami Equation; the “Additivity Rule” Revisited	445
9.6.12	The Effective Activation Energy	447
9.6.13	Experimental Determination of the Degree of Transformation; Dilatometry and Calorimetry	448
9.6.14	Fitting of Kinetic Models	451
9.6.15	Direct Determination of the Effective Activation Energy and the Growth Exponent	453
9.7	The Coupling of Thermodynamics to Kinetics	459
	References	460
10	Recovery, Recrystallization and Grain Growth	463
10.1	Recovery	463
10.1.1	Dislocation Annihilation and Rearrangement	465
10.1.2	Kinetics of Recovery	469
10.2	Recrystallization	470
10.2.1	“Nucleation” of Recrystallization	471
	<i>Intermezzo: The History of an Idea; the Subgrain as Origin of Recrystallization</i>	<i>475</i>
10.2.2	Kinetics of Recrystallization	476
10.3	Grain Growth	477
10.3.1	The Grain-Boundary Network; on Grain-Boundary/Interfacial Energy and Tension	478
	<i>Intermezzo: Interface Stabilized Microstructures</i>	<i>483</i>
10.3.2	Grain-Boundary Curvature-Driven Growth	484
10.3.3	Kinetics of Grain Growth; Inhibition of Grain Growth	487
10.3.4	Abnormal Grain Growth	491
10.3.5	Particle Coarsening; Ostwald Ripening	493
	References	495
11	Mechanical Strength of Materials	497
11.1	Elastic Versus Plastic Deformation; Ductile and Brittle Materials	498
11.2	Basic Modes of Uniaxial Deformation; Concepts of Stress and Strain; Uniaxial Elastic Deformation Laws	499
	<i>Intermezzo: Short History of the Poisson Constant</i>	<i>502</i>
	<i>Intermezzo: Negative Poisson Constant</i>	<i>503</i>
11.3	Elastically Isotropic and Anisotropic Materials	504
11.4	Elastic Deformation Upon Three-Axial and Biaxial Loading	507
11.5	Elastic Strain Energy	512
11.6	Rubber Elasticity; Elastomeric Behaviour	514
11.7	Viscoelasticity/Anelasticity; Mechanical Hysteresis	516

11.8	Plastic Deformation Characteristics	519
11.9	The Tensile Stress–Strain Curve; True Stress and True Strain	521
11.9.1	Strain and Strain Rate Due to Dislocation Movement	525
11.9.2	The Yield Drop Phenomenon; Cottrell-Bilby Atmospheres	526
11.9.3	Shear Yielding and Craze Yielding	531
11.10	Yielding Criteria in Cases of Two- and Three-Axial Loading	532
	<i>Intermezzo: Application of the von Mises Criterion to Predict the Location of Failure in Ball Bearings</i>	<i>533</i>
11.11	Critical Resolved Shear Stress; the Plastic Deformation of Single Crystals	536
11.12	Plastic Deformation of Polycrystals	539
11.13	Hardness Parameters; Macroscopic, Microscopic and Nanoscopic	540
	<i>Intermezzo: The Hardest Materials</i>	<i>542</i>
	<i>Intermezzo: Combined Nanoindentation and Scanning Probe Microscopy</i>	<i>544</i>
	<i>Intermezzo: Hardness-Depth Profiling on Nanoscale</i>	<i>548</i>
11.14	Strengthening, Hardening Mechanisms (of Metals in Particular)	550
11.14.1	Strain Hardening (Work Hardening)	550
11.14.2	Grain Size; the Hall–Petch Relation	551
11.14.3	Solid Solution Hardening	554
11.14.4	Precipitation/Dispersion Strengthening	555
11.15	Failure by Fracture; Crack Propagation	557
11.16	Failure by Creep	562
11.16.1	Superplasticity	566
11.17	Failure by Fatigue	567
11.18	Residual, Internal Stresses	573
	<i>Epilogue: The Essence of Materials Science; Optimizing the Fatigue Strength of Ferritic Steels by Nitriding</i>	<i>576</i>
	References	580
Index		583