

CONTENTS

<i>Foreword</i>	vii
<i>Preface</i>	ix
<i>Acknowledgements</i>	xii

1. Introduction 1

1. NDT an Age Old Practice	1
2. Ultrasonic NDT	3
2.1 Advantages and Limitations of Ultrasonic NDT	4
2.2 Ultrasonic Transducer for NDT	4
2.2.1 Status at National Level	6
2.2.2 General Comments	6
References	7

2. Propagation of Ultrasonic Waves 8

1. Introduction	8
2. Sound Waves and Physical Principles	8
2.1 Longitudinal Waves	10
2.2 Transverse Waves	11
2.3 Beam at Normal Incidence	12
2.4 Acoustic Impedance	12
3. Reflection, Refraction and Mode Conversion	14
3.1 Beam at an Angle	14
3.1.1 Reflection and Transmission Coefficient at Oblique Incidence	15
3.2 Critical Angles and other Types of Waves	15
3.3 First Critical Angle	15
3.4 Creeping Waves	16
3.5 Second Critical Angle	17
3.6 Surface Waves	18
3.7 Lamb Waves	19
4. Beam Profile	20
4.1 Near Field	21
4.2 Far Field	22
4.3 Divergence of Beam	22
5. Loss of Energy and Attenuation	23
5.1 Scattering	24
5.2 Absorption	24
References	25

3. Testing Techniques**26**

1. Introduction 26
2. Methods of Testing 26
 - 2.1 Pulse Echo Method 26
 - 2.1.1 Contact Method 27
 - 2.1.2 Immersion Method 29
 - 2.2 Two Transducer Method 29
 - 2.3 Through Transmission Method 30
 - 2.4 Resonance Method 31
3. Comparison of Contact and Immersion Methods 33
4. Longitudinal and Shear Wave Inspection 34
 - 4.1 Longitudinal Wave Inspection 34
 - 4.2 Shear Wave Inspection 35
 - 4.3 Significance of Critical Angles 40
5. Rayleigh and Lamb Wave Inspection 42
 - 5.1 Applications in NDT 42
- References 43

4. Probe Heads**44**

1. Introduction 44
2. Flaw Detector Unit 44
 - 2.1 Basic Parts 45
 - 2.2 Methods of Presentation 46
 - 2.2.1 A-Scan Presentation 46
 - 2.2.2 B-Scan Presentation 46
 - 2.2.3 C-Scan Presentation 46
3. Transducer or Probe Head 48
 - 3.1 Active Element 48
 - 3.2 Backing Material 49
 - 3.3 Front Plate and Matching Layer 50
4. Transducer Characteristics 51
 - 4.1 Sensitivity 51
 - 4.2 Resolution 52
 - 4.3 Dead Zone 54
5. Probe Selection 54
 - 5.1 Size of the Probe 54
 - 5.2 Contour Matching Soles 55
 - 5.3 Frequency 56
 - 5.3.1 Grain Size and Flaw Size 58
6. Normal Beam Transducers 58
 - 6.1 Contact Type Probe 59
 - 6.1.1 Normal Longitudinal Wave Probe (NLW Probe) 59
 - 6.1.2 Normal Shear Wave Probe (NSW Probe) 59
 - 6.2 Immersion Probes 61
 - 6.3 Low Frequency Transducer 62
 - 6.3.1 Design Considerations 62
 - 6.4 High Temperature Probes 63
7. Angle Beam Probes 64
 - 7.1 Angle Beam and Surface Wave Transducers 64
 - 7.1.1 Frequency Considerations 66

7.1.2.	Skip Distance	67
7.2	Variable Angle Beam Probes	68
7.3	Longitudinal Angle Beam Probes	69
7.4	Creeping Wave Transducers	70
8.	Twin Element Probes	71
8.1	Types of Twin Probes	72
8.2	Design Considerations	75
8.3	Nonlinearity and Other Considerations	76
9.	Focused Transducers	79
9.1	Immersion Methods	79
9.2	Methods of Focussing Ultrasonic Beam	82
9.3	Transducers with Curved Front Face	83
9.3.1	Design of Lens and Its Material	83
9.3.2	Types of Lenses	84
9.3.3	Degree of Focussing	86
9.3.4	Beam Diameter	86
9.4	Fresnel Zone Plate	87
9.5	Phased Arrays	88
9.5.1	Linear Arrays	89
9.5.2	Planar Arrays	90
9.5.3	Annular Arrays	90
	References	91

5. Transducer Materials

94

1.	Introduction	94
2.	Piezoelectric Materials	94
3.	Single Crystal Materials	95
3.1	Quartz	95
3.2	Advantages and Limitations of Quartz.	97
3.3	Lithium Sulphate	97
4.	Piezoceramic Materials	98
4.1	Barium Titanate and Lead Zirconate Titanate	99
4.2	Lead Metaniobate	99
4.3	Process of Manufacture.	99
4.3.1	Weighing, Mixing & Calcining	100
4.3.2	Pressing and Sintering	100
4.3.3	Lapping and Shaping	101
4.3.4	Electroding	101
4.3.5	Poling	103
4.3.6	Aging and Testing	104
5.	Polymer Materials	104
5.1	Preparation of PVDF Films	104
5.2	Advantages and Limitations of PVDF	106
6.	Composite Materials	107
	References	108

6. Piezoceramic Material Parameters and Their Measurement

110

1.	Introduction	110
2.	Piezoelectric Behaviour	111

2.1	Direct Piezoelectric Effect	111
2.2	Reverse Piezoelectric Effect	111
2.3	Static Performance	113
2.4	Notations and Subscripts	114
2.5	Dynamic Performance	115
3.	Type Designation	116
3.1	Barium Titanate Based Piezoceramic	117
3.2	Lead Zirconate Titanate	117
3.2.1	Type 4	117
3.2.2	Type 5	117
3.2.3	Type 5H	118
3.2.4	Type 6 & 7	118
3.2.5	Type 8	118
4.	Modes of Oscillations	119
5.	Material Parameters and Their Measurements	120
5.1	Frequency of Minimum and Maximum Impedance	121
5.2	Methods of Measurements of the Properties of Piezoceramics	122
5.2.1	Density	122
5.2.2	Dielectric Constant	123
5.2.3	Dissipation Factor	123
5.2.4	Resistivity	123
5.2.5	Planar Coupling Coefficient	123
5.2.6	Piezoelectric Charge Constant	124
5.2.7	Piezoelectric Voltage Constant	124
5.2.8	Frequency Constant	125
5.2.9	Mechanical Quality Factor	125
5.2.10	Curie Temperature	125
	References	127

7. Performance Evaluation of NDT Transducers 128

1.	Introduction	128
2.	Visual Examination	128
2.1	Face Flatness	129
3.	Some Important Parameters	129
3.1	Linearity of Time Base	129
3.2	Linearity of Amplifier	131
3.3	Relative Penetrating Power	132
3.4	Resolving Power	133
3.5	Determination of Probe Index	134
3.6	Determination of Beam Angle	135
3.7	Beam Profile	135
3.7.1	Normal Beam Probe	137
	(a) Checking the Acoustical Axis	137
	(b) Beam Profile Measurement	137
3.7.2	Angle Beam Probe	137
	(a) Beam Profile in Vertical Plane	137
	(b) Beam Profile in Horizontal Direction	139
3.8	Squint (Beam Alignment)	140
3.8.1	Normal Beam Probe	140
3.8.2	Angle Beam Probe	141

3.9	Estimation of Dead Zone	142
4.	Electrical and Acoustical Parameters	143
4.1	Measurement of Frequency Response	143
4.1.1	Methods of Excitation	143
	(a) Shock Excitation Technique	144
	(b) Sinusoidal Burst Technique	144
4.1.2	Experimental Setup for Contact Probes	144
4.1.3	Experimental Setup for Immersion Type Probes	144
4.1.4	Recording	146
4.2	Bandwidth Measurement	146
4.3	Relative Sensitivity	146
4.4	Electrical Impedance Measurements	148
4.5	Sound Field Measurement	148
4.5.1	Test Setup	149
4.5.2	Experimental Measurement	149
4.5.3	Focused Immersion Probes	150
	4.5.3.1 Focal length and Depth of Focus	150
	4.5.3.2 Diameter at Focal Point	150
5.	Method of Observing Beam Shapes	151
5.1	Dry Paper Recording	152
5.2	Beam Plotting in Water	152
5.3	Photoelastic Evaluation	153
	References	154

8. Calibration Blocks for Ultrasonic NDT 155

1.	Introduction	155
2.	Calibration Blocks and Reference Blocks	156
3.	Blocks Containing Natural Flaws	156
4.	Blocks With Artificial Flaws	157
4.1	Material	157
4.2	Fabrication	157
5.	Calibration Blocks	158
5.1	International Institute of Welding (IIW) Calibration Block	159
5.2	Miniature Calibration Block	159
5.3	IOW Beam Profile and Resolution Block	160
5.4	Multipurpose Calibration Block	160
5.5	Block for Resolving Power	162
5.6	Step Wedge	162
	5.6.1 Ladder Step Wedge	163
	5.6.2 LSW with Steel Inserts	163
	5.6.3 Curved Step Wedge	163
5.7	Surface Wave Block	166
	5.7.1 Reflecting Targets	166
6.	Other Alternative Blocks	166
6.1	Shear Wave Probe Block (ESI)	166
6.2	Standard Weld Specimen	168
6.3	Distance Calibration Block (DC)	168
6.4	Sensitivity Calibration Block (SC)	168
6.5	Distance and Sensitivity Calibration Block (DSC)	169
6.6	Basic Calibration Block (ASME)	171

- 7. Flat Bottom Hole (FBH) Blocks 172
 - 7.1 Area-Amplitude Blocks 173
 - 7.2 Distance-Amplitude Blocks 175
 - 7.3 Distance-Area-Amplitude Blocks 175
 - 7.4 Sensitivity-Resolution Blocks 176
- 8. General Remarks 177
- References 178

9. Acoustic Coupling Techniques

180

- 1. Introduction 180
- 2. Contact Methods 181
 - 2.1 General Considerations 181
 - 2.1.2 Surface Condition 181
 - 2.1.2 Requirements of a Good Couplant 182
 - 2.1.3 Choice of Couplant 183
 - 2.1.4 Pressure on Probe 184
 - 2.2 Free Flow Coupling Techniques 184
 - 2.3 Dry Pressure Coupling Techniques 184
 - 2.3.1 Rubber Pad Coupling 184
 - 2.3.2 Liquid Filled Pad or Wheel 185
 - 2.3.3 Testing of Materials having Porous Structure 187
 - 2.4 Solid Coupling 187
 - 2.5 Coupling for Normal Shear Wave (NSW) Probes 188
- 3. Immersion Method 188
- 4. Water Path Methods 189
- 5. Coupling at High Temperatures 190
 - 5.1 General Considerations 190
 - 5.2 Temperature Gradient Methods 191
 - 5.2.1 Temperature Gradient in Coupling Path 191
 - 5.2.2 Temperature Gradient in Work Piece 192
 - 5.2.3 Dry Contact Method 193
 - 5.2.4 Momentary Contact Method 194
- 6. Non-Contact Methods of Coupling 195
 - 6.1 Use of EMATs and LGU Techniques 195
 - 6.2 Air Coupling 195
- References 196

10. Other Methods of Transduction of Ultrasound

197

- 1. Introduction 197
- 2. Electromagnetic Acoustic Transducers (EMATs) 197
 - 2.1 Physical Principle 199
 - 2.2 Generation of Various Types of Waves 201
 - 2.2.1 Longitudinal and Shear-Wave Generation 201
 - 2.2.2 Surface Wave Generation 202
 - 2.3 Special Applications 204
- 3. Laser Generated Ultrasonics (LGU) 204
 - 3.1 Physical Principles 205
 - 3.1.1 Thermoelastic Generation of Ultrasonics 205
 - 3.1.2 Generation of ultrasonics in Ablation Regime 205
 - 3.1.3 Generation of LGU at an Angle 206

3.2	Advantages and Limitations of LGU	207
3.3	Applications	209
3.3.1	Calibration Work	209
3.3.2	Material Characterization	209
3.3.3	Flaw Detection	210
	References	211

APPENDICES

1. Appendix A. Some Useful Data 212

A.1	Density, Velocity and Acoustic Impedance of Some Common Materials.	212
A.2	Properties of Some Transducer Materials used in NDT Probes.	213
A.3	Properties of Some Other Piezoelectric Ceramic Materials Along With Tolerances	213
A.4	Tolerances on Various Dimensions of Piezoelectric Bodies for Transducers	214
A.5	Guidelines for Selection of Test Frequency.	214
A.6	Approximate Attenuation Coefficients and Useful Depths of Inspection, for Various Metallic and Nonmetallic Materials.	215
A.7	Variation of Wavelength (in mm) in Some Common Materials With Frequency.	216
A.8	Near Field Length (in mm) in Some Common Materials with Frequency and Diameter	217

2. Appendix B. Standards and Specifications 218

B.1	Bureau of Indian Standards (BIS)	218
B.2	American Society for Testing and Materials (ASTM)	219
B.3	British Standards Institution (BSI)	220

3. Appendix C. Glossary of Terms 221

References	228
------------	-----

Subject Index 229