

Contents

Page

Foreword	v
Introduction	vi
1 Scope	1
2 Normative references	1
3 Terms and definitions	2
4 Classification of scaler handpieces	3
5 Requirements and performance	3
5.1 General	3
5.2 Materials	3
5.3 Drop test	3
5.4 Noise level	3
5.5 Surfaces	4
5.6 Electrical power supply (if applicable)	4
5.7 Energy for light source (if applicable)	4
5.8 Air supply	4
5.9 Supply of cooling liquid	4
5.10 Air and water pressure	4
5.11 Temperature	4
5.11.1 Temperature rise of housing	4
5.11.2 Temperature, excessive	5
5.12 Vibrations	5
5.13 Resistance to reprocessing	5
5.14 Leakage and/or ingress of water	5
5.15 Electromagnetic compatibility	5
5.16 Operating controls	5
5.17 Usability	5
5.18 Connection	6
5.18.1 General	6
5.18.2 Connections for air-powered scaler handpieces	6
5.18.3 Connector for electrical-powered scaler handpieces	6
5.19 Scaler tip performance	6
5.19.1 Scaler tip connection	6
5.19.2 Extraction force (for non-screw tips only)	6
5.19.3 Holding torque (for screw-in-tips only)	6
5.19.4 Insertion force (for non-screw-tips only)	7
5.19.5 Tightening torque (for screw-in-tips only)	7
5.19.6 Stall effort	7
5.19.7 Power output, scaler tips	7
5.19.8 Breakage resistance	7
5.20 Frequency	7
5.21 Amplitude	7
6 Sampling	7
7 Testing	8
7.1 General test conditions	8
7.2 Visual inspection	8
7.3 Power supply — Electrical	8
7.4 Air supply	8
7.4.1 Apparatus	8
7.4.2 Procedure	8
7.5 Supply of cooling liquid	8
7.5.1 Apparatus	8
7.5.2 Procedure	8

7.6	Air and water pressure	8
7.6.1	Apparatus	8
7.6.2	Procedure	8
7.7	Measuring device for dimensions	9
7.8	Scaler tips	9
7.8.1	Extraction force (for non-screw-tips only)	9
7.8.2	Holding torque (for screw-in-tips only)	9
7.8.3	Insertion force (for non-screw-tips only)	9
7.8.4	Tightening torque (for screw-in-tips only)	9
7.8.5	Stall effort	10
7.8.6	Power output, scaler tips	10
7.8.7	Breakage resistance	12
7.9	Frequency	12
7.9.1	Apparatus	12
7.9.2	Procedure	12
7.10	Amplitude	12
7.10.1	Apparatus	13
7.10.2	Procedure	13
7.11	Noise level	13
7.11.1	Apparatus	14
7.11.2	Test conditions	14
7.11.3	Procedure	14
7.12	Temperature rise of housing	14
7.13	Temperature, excessive	14
7.14	Resistance to reprocessing	14
8	Instructions for use, maintenance and service	14
9	Technical description	15
10	Marking	15
10.1	General	15
10.2	Scaler handpieces	15
10.3	Scaler tips	16
11	Labelling	16
12	Packaging	16
	Annex A (informative) Calculation example for power output	17