

Contents	Page
Foreword.....	iv
1 Scope.....	1
2 Normative references.....	1
3 Terms and definitions.....	1
4 Principle.....	2
5 Reagents and materials.....	3
5.1 Cleaning solvents.....	3
6 Apparatus.....	3
6.1 Four-ball extreme-pressure lubricant testing machine.....	3
6.2 Friction recording device (optional).....	5
6.3 Loading discs.....	5
6.4 Microscope.....	5
6.5 Timer.....	5
6.6 Test balls.....	6
6.7 Assembly device.....	6
7 Samples and sampling.....	6
8 Preparation of apparatus.....	6
9 General procedure.....	6
10 Test procedures.....	7
10.1 Mean Hertz load (MHL).....	7
10.2 Wear-load curve, welding load, flash temperature parameter and initial seizure load.....	8
10.3 Wear test.....	8
11 Calculations.....	8
11.1 General.....	8
11.2 Mean Hertz load.....	8
11.3 Wear-load curve, flash temperature parameter and initial seizure load.....	9
12 Expression of results.....	10
13 Precision.....	10
13.1 General.....	10
13.2 Repeatability.....	11
13.3 Reproducibility.....	11
14 Test report.....	11
Annex A (normative) Mean Hertz load data sheet.....	12
Annex B (normative) Calibration of friction recorder springs.....	14
Bibliography.....	17

NOTE Under conditions of low load and low friction, wear causes only small circular scars on the three stationary balls and a ring on the rotating ball. The diameters of these scars are slightly larger than the diameter of the indentation due to the static load (Hertz diameter).