

Contents

	Volume 2	
	Preface V	
	List of Contributors XV	
3	Characterization of Solid Catalysts 721	
3.1	Physical Properties 721	
3.1.1	Surface Area and Porosity 721 <i>Alexander V. Neimark, Kenneth S. W. Sing, and Matthias Thommes</i>	
3.1.1.1	Introduction 721	
3.1.1.2	Physisorption of Gases 722	
3.1.1.2.1	Determination of Surface Area 723	
3.1.1.2.2	Assessment of Porosity 726	
3.1.1.3	Adsorption at the Liquid–Solid Interface 733	
3.1.1.3.1	Adsorption from Solution 733	
3.1.1.3.2	Heat of Immersion 734	
3.1.1.4	Mercury Porosimetry 735	
3.1.1.5	General Conclusions 736	
	References 736	
3.1.2	Particle Size and Dispersion Measurements 738 <i>G�rard Bergeret and Pierre Gallezot</i>	
3.1.2.1	Definitions and Generalities 738	
3.1.2.1.1	Particles 738	
3.1.2.1.2	Particle Size 739	
3.1.2.1.3	Nuclearity of Particles 739	
3.1.2.1.4	Dispersion 739	
3.1.2.1.5	Relationships Between Particle Size, Surface Area and Dispersion 739	
3.1.2.1.6	Methods of Particle Size Measurement 741	
3.1.2.2	Particle Size Measurements by Gas Chemisorption 741	
3.1.2.2.1	Introduction and Principles 741	
3.1.2.2.2	Gas Adsorption–Desorption Methods 742	
3.1.2.2.3	Choice of Adsorbate Gases 744	
3.1.2.2.4	Hydrogen Chemisorption; Hydrogen–Oxygen Titration 744	
3.1.2.2.5	Conclusion and Recommendations 746	
3.1.2.3	X-Ray Diffraction Line Broadening Analysis 746	
3.1.2.3.1	Introduction 746	
3.1.2.3.2	Elementary Line Broadening Analysis: the Scherrer Equation 746	
3.1.2.3.3	Complete Line Profile Analysis: the Warren–Averbach Method 747	
3.1.2.3.4	Examples of Application of Classical LBA to Catalysts 747	
3.1.2.3.5	Whole-Powder Pattern Fitting Methods: the Rietveld Refinement 748	
3.1.2.3.6	Limits of Application of Methods 749	
3.1.2.3.7	Conclusion 750	
3.1.2.4	Small-Angle X-Ray Scattering Analysis 750	
3.1.2.4.1	Introduction 750	
3.1.2.4.2	Specific Surface Area Measurements: Porod’s Law 751	
3.1.2.4.3	Mean Size Parameters: Guinier Radius 751	
3.1.2.4.4	Calculation of Size Distribution 751	
3.1.2.4.5	Application of SAXS to Metal Particle Size Determination in Supported Catalysts 752	
3.1.2.4.6	Anomalous Small-Angle X-Ray Scattering (ASAXS) 753	
3.1.2.4.7	Conclusion 754	
3.1.2.5	Determination of Particle Size by Electron Microscopy 754	
3.1.2.5.1	Scope 754	
3.1.2.5.2	Fundamentals of Imaging and Contrast 755	
3.1.2.5.3	Preparation of Samples for TEM and STEM Examination 756	
3.1.2.5.4	Particle Size Measurement 757	
3.1.2.5.5	Selected Examples of Particle Size Distribution 759	

3.1.2.5.6	Selected Examples of 3D Localization of Particles in Supports by Electron Tomography	761	3.1.3.4.6	Imaging of Oxide Surfaces	850
3.1.2.6	Particle Size Measurements by Magnetic Methods	761	3.1.3.4.7	Catalyst Design Based on Model System Studies	859
	References	763	3.1.3.4.8	Conclusion	865
				References	866
3.1.3	Structure and Morphology	765	3.1.3.5	Heterogeneous Catalysis and High Electric Fields	870
3.1.3.1	X-Ray Powder Diffraction	765		<i>Norbert Kruse and Thierry Visart de Bocarmé</i>	
	<i>Daniel Herein</i>		3.1.3.5.1	Introduction	870
3.1.3.1.1	Introduction	765	3.1.3.5.2	Electric Fields	870
3.1.3.1.2	Phase Analysis	766	3.1.3.5.3	Applications in Fundamental Research on Heterogeneous Catalysis	875
3.1.3.1.3	Peak Profile Analysis	769	3.1.3.5.4	Field-Induced Surface Phenomena	890
3.1.3.1.4	Full X-Ray Powder Pattern Analysis	770	3.1.3.5.5	Field-Induced Phenomena at Extended Surfaces and Interfaces	891
3.1.3.1.5	<i>In Situ</i> X-Ray Powder Diffraction	770	3.1.3.5.6	Conclusion	892
3.1.3.1.6	Conclusion	773		References	892
	References	773			
3.1.3.2	Applications of X-Ray Absorption Spectroscopy in Heterogeneous Catalysis: EXAFS, Atomic XAFS and Delta XANES	774	3.1.3.6	Gamma Spectroscopies	895
	<i>Diek C. Koningsberger and Dave E. Ramaker</i>			<i>Hans Niemantsverdriet and Tilman Butz</i>	
3.1.3.2.1	Introduction	774	3.1.3.6.1	Introduction	895
3.1.3.2.2	Physical Principles of X-Ray Adsorption and Electron Scattering	775	3.1.3.6.2	Mössbauer Spectroscopy	896
3.1.3.2.3	Isolating the Oscillatory Part ($\chi_{AX} + \chi_{EX}$) from the Absorption Data	776	3.1.3.6.3	Time-Differential Perturbed Angular Correlations (TDPAC)	903
3.1.3.2.4	EXAFS	778	3.1.3.6.4	Conclusions and Outlook	910
3.1.3.2.5	Atomic XAFS (AXAFS)	788		References	911
3.1.3.2.6	Δ XANES Technique	795	3.1.3.7	Solid-State NMR Spectroscopy	912
	References	802		<i>Michael Hunger and Wei Wang</i>	
3.1.3.3	Electron Microscopy Techniques	803	3.1.3.7.1	Introduction	912
	<i>Abhaya K. Datye, Poul Lervig Hansen, and Stig Helveg</i>		3.1.3.7.2	Interactions of Nuclear Spins in Solids	912
3.1.3.3.1	Introduction	803	3.1.3.7.3	Experimental Techniques of Solid-State NMR Spectroscopy	914
3.1.3.3.2	Imaging	803	3.1.3.7.4	Preparation of Catalyst Samples for Solid-State NMR Spectroscopy	917
3.1.3.3.3	Electron Diffraction	821	3.1.3.7.5	NMR Investigations of Catalyst Frameworks	918
3.1.3.3.4	Electron Beam Microanalysis	823	3.1.3.7.6	NMR Investigations of Heterogeneously Catalyzed Reactions	925
3.1.3.3.5	<i>In Situ</i> Electron Microscopy	826	3.1.3.7.7	Conclusions	929
3.1.3.3.6	Summary and Conclusions	831		References	930
	References	832			
3.1.3.4	Scanning Probe Methods	833	3.1.3.8	Vibrational Spectroscopies	932
	<i>Flemming Besenbacher, Jeppe Vang Lauritsen, and Ronnie T. Vang</i>			<i>Gerhard Mestl and Helmut Knözinger</i>	
3.1.3.4.1	Introduction	833	3.1.3.8.1	Introduction	932
3.1.3.4.2	Scanning Probe Techniques	834	3.1.3.8.2	Basic Principles of Vibrational Spectroscopies	932
3.1.3.4.3	High-Resolution STM Studies	836	3.1.3.8.3	Vibrational Spectra of Bulk Oxides	937
3.1.3.4.4	Dynamic Imaging	838	3.1.3.8.4	Vibrational Spectra of Supported Catalysts	955
3.1.3.4.5	High-Pressure STM Studies	846			

3.1.3.8.5	Vibrational Spectra of Surface and Structural Hydroxy Groups	959	References	965	3.2	Chemical Properties	1000
3.1.3.9	Neutron Scattering	971	<i>Hervé Jobic</i>		3.2.1	Bulk Chemical Composition	1000
3.1.3.9.1	Introduction	971				<i>Peter W. Albers</i>	
3.1.3.9.2	Interaction of Neutrons with Matter	971			3.2.1.1	Introduction	1000
3.1.3.9.3	Experimental	972			3.2.1.2	Bulk Sampling	1001
3.1.3.9.4	Structure	974			3.2.1.3	Analytical Techniques	1002
3.1.3.9.5	Dynamics	974			3.2.1.3.1	Fire Assay	1002
3.1.3.9.6	Conclusions	981			3.2.1.3.2	From Classical Methods to Instrumental Analysis	1003
	References	981			3.2.1.3.3	X-Ray Techniques	1004
3.1.3.10	Morphological Characteristics	982	<i>Friedrich Schmidt</i>		3.2.1.3.4	Atomic Absorption and Emission Spectroscopy and Inorganic Mass Spectrometry	1005
3.1.3.10.1	Introduction	982			3.2.1.3.5	Elemental Analysis	1006
3.1.3.10.2	Morphological Characteristics of Catalyst Beds	983			3.2.1.4	Examples of Bulk Chemical Analytical Procedures on Catalysts	1006
3.1.3.10.3	Size and Shape of Catalyst Powder Particles and their Morphological Parameters	985			3.2.1.4.1	Three Steps in the Determination of Ag in Recycling of 10–13% Ag/ α -Al ₂ O ₃ Pellets Used in the Oxidation of Ethylene	1006
3.1.3.10.4	Morphology of Bulk and Eggshell Catalysts	991			3.2.1.4.2	Pd/Activated Carbon Catalysts	1006
3.1.3.10.5	Morphology of Bulk Honeycombs and Other Bulk Monoliths	991			3.2.1.4.3	Characterization of Used Pd/Au/SiO ₂ or Pd/Al ₂ O ₃ Fixed-Bed Catalysts	1006
3.1.3.10.6	Morphology of Catalysts on the Micrometer Scale	994			3.2.1.4.4	Pt, Ir, Re/ γ -Al ₂ O ₃ Reforming Catalysts	1007
3.1.3.10.7	Morphology of Catalysts on the Nanometer and Sub-Nanometer Scale	995			3.2.1.4.5	Sulfur Analysis of Exhaust Gas Purification Catalysts	1007
	References	997			3.2.1.5	Reference Materials and Round Robins	1007
3.1.4	Mechanical Properties	997	<i>Friedrich Schmidt</i>		3.2.1.5.1	Reference Materials	1007
3.1.4.1	Introduction	997			3.2.1.5.2	Round Robins	1007
3.1.4.1.1	General Considerations	997			3.2.1.6	Quantitative Analysis at the Macroscopic Scale	1009
3.1.4.1.2	Causes of Mechanical Damage	997			3.2.1.6.1	Distribution Profiles from Nanometer to Centimeter Level	1009
3.1.4.1.3	Mechanical Resistance of Catalysts – Definitions	998			3.2.1.6.2	Macroscopic Element Distribution Profiles in the Centimeter Range	1011
3.1.4.2	Determination of Crush Strength (Break Strength)	998			3.2.1.6.3	Macroscopic PGM Distribution Profiles in the Centimeter Range	1012
3.1.4.2.1	Crush Strength of Individual Grains	998			3.2.1.6.4	Hydrogen Analysis of Macroscopic Samples	1012
3.1.4.2.2	Bulk Crush Strength (Bed Crushing Strength) or Shell Test	998			3.2.1.7	Conclusion	1012
3.1.4.2.3	Impact or Drop Test	998				References	1013
3.1.4.3	Determination of Attrition Resistance	998			3.2.2	Surface Chemical Composition	1014
3.1.4.3.1	Grains or Powders	1000				<i>Edmund Taglauer</i>	
3.1.4.3.2	Attrition Resistance of Coated Monoliths	1000			3.2.2.1	Introduction	1014
3.1.4.4	Adhesiveness of Coatings	1000			3.2.2.2	Electron Spectroscopies (AES, XPS)	1015
	References	1000			3.2.2.2.1	Basic Aspects	1015
					3.2.2.2.2	Auger Electron Spectroscopy (AES)	1017
					3.2.2.2.3	X-Ray Photoemission Spectroscopy (XPS)	1018
					3.2.2.3	Ion Scattering Spectroscopies	1021
					3.2.2.3.1	General Aspects	1021

3.2.2.3.2	Collision Kinematics	1021	3.2.3.3.4	Conclusions	1072
3.2.2.3.3	Low-Energy Ions	1022		References	1072
3.2.2.3.4	Rutherford Scattering	1024	3.2.3.4	Muon Spin Spectroscopy of Transient Radicals in Zeolites	1073
3.2.2.4	Secondary Particles	1025		<i>Ian McKenzie and Emil Roduner</i>	
3.2.2.4.1	Secondary Ion Mass Spectrometry	1025	3.2.3.4.1	Introduction	1073
3.2.2.4.2	Secondary Neutrals	1026	3.2.3.4.2	The Positive Muon, Muonium and Muoniated Radicals	1073
3.2.2.4.3	Photon Stimulation	1026	3.2.3.4.3	Experimental Techniques	1074
	References	1027	3.2.3.4.4	μ SR Studies of Radicals in Zeolites	1076
			3.2.3.4.5	Conclusions	1079
				References	1079
3.2.3	Valence States	1029	3.2.3.5	Temperature-Programmed Reduction and Oxidation	1080
3.2.3.1	X-Ray Photoelectron and Auger Electron Spectroscopy	1029		<i>Helmut Knözinger</i>	
	<i>Giuliano Moretti</i>		3.2.3.5.1	Introduction	1080
3.2.3.1.1	Introduction	1029	3.2.3.5.2	The TPR Experiment	1080
3.2.3.1.2	X-Ray and UV Photoelectron Spectroscopy	1029	3.2.3.5.3	Kinetics and Mechanism of Reduction	1082
3.2.3.1.3	Auger Electron Spectroscopy	1030	3.2.3.5.4	Mathematical Treatment of TPR Profiles and Influence of Experimental Parameters	1084
3.2.3.1.4	Surface Sensitivity	1030	3.2.3.5.5	Examples	1084
3.2.3.1.5	Reference Level	1031	3.2.3.5.6	Conclusion	1094
3.2.3.1.6	Chemical Shifts in XPS and AES	1032		References	1095
3.2.3.1.7	Wagner Plots	1034	3.2.4	Acidity and Basicity	1096
3.2.3.1.8	Thermochemical Approach	1036	3.2.4.1	Concepts and Analysis of Acidity and Basicity	1096
3.2.3.1.9	Illustrative Examples of Application of XPS and AES-XAES to Heterogeneous Catalysis	1037		<i>Hellmut G. Karge</i>	
	References	1038	3.2.4.1.1	Introduction	1096
			3.2.4.1.2	Concepts of Acidity and Basicity of Zeolite and Oxide Catalysts	1097
3.2.3.2	UV-Vis-NIR and EPR Spectroscopies	1039	3.2.4.1.3	Analysis of Acidity and Basicity	1101
	<i>Zbigniew Sojka, Francois Bozon-Verduraz, and Michel Che</i>		3.2.4.1.4	Conclusion	1117
3.2.3.2.1	Introduction	1039		References	1118
3.2.3.2.2	UV-Vis-NIR Spectroscopy	1040	3.2.4.2	Thermochemical Characterization	1122
3.2.3.2.3	EPR Spectroscopy	1051		<i>Nelson Cardona Martínez and James A. Dumesic</i>	
3.2.3.2.4	Comparison between UV-Vis-NIR (DRS) and EPR Spectroscopies	1062	3.2.4.2.1	Introduction	1122
3.2.3.2.5	Conclusions	1062	3.2.4.2.2	Principles of Temperature-Programmed Desorption	1123
	References	1063	3.2.4.2.3	Applications of Temperature-Programmed Desorption	1124
			3.2.4.2.4	Principles of Adsorption Microcalorimetry	1126
3.2.3.3	Photoluminescence Spectroscopy and Its Application to the Characterization of Active Sites and Reaction Dynamics in Catalysis	1065	3.2.4.2.5	Applications of Adsorption Microcalorimetry	1127
	<i>Masaya Matsuoka, Takashi Kamegawa, and Masakazu Anpo</i>				
3.2.3.3.1	Introduction	1065			
3.2.3.3.2	Characterization of Catalysts by Photoluminescence and Time-Resolved Photoluminescence Spectroscopy	1066			
3.2.3.3.3	Investigations of the Dynamics of Photocatalysis by Time-Resolved Photoluminescence Spectroscopy	1068			

3.2.4.2.6	Conclusions	1133	3.2.6.6	Hydrogen Content and Hydrogen Analysis	1210
	References	1133	3.2.6.7	Hydrogasification	1213
3.2.4.3	Infrared Spectroscopy for the Characterization of Surface Acidity and Basicity	1135	3.2.6.8	Conclusions	1214
	<i>Helmut Knözinger</i>			References	1214
3.2.4.3.1	Introduction	1135	3.3	IUPAC Recommendations	1217
3.2.4.3.2	Criteria for the Selection of Probe Molecules	1135	3.3.1	Reporting Physisorption Data for Gas/Solid Systems	1217
3.2.4.3.3	Characterization of Acid Sites on Solid Catalysts	1137		<i>Kenneth S. W. Sing, Douglas H. Everett, R. A. W. Haul, L. Moscou, Robert A. Pierotti, Jean Rouquerol, and Teresa Siemieniewska</i>	
3.2.4.3.4	Characterization of Basic Sites on Solid Catalysts	1155	3.3.1.1	Introduction	1217
3.2.4.3.5	Conclusion	1157	3.3.1.2	General Definitions and Terminology	1217
	References	1158	3.3.1.3	Methodology	1219
3.2.4.4	NMR Spectroscopy for the Characterization of Surface Acidity and Basicity	1163	3.3.1.3.1	Methods for the Determination of Adsorption Isotherms	1219
	<i>Michael Hunger</i>		3.3.1.3.2	Operational Definitions of Adsorption	1219
3.2.4.4.1	Introduction	1163	3.3.1.4	Experimental Procedures	1221
3.2.4.4.2	Investigation of Brønsted Acidic Hydroxyl Groups by ^1H MAS NMR Spectroscopy	1164	3.3.1.4.1	Outgassing the Adsorbent	1221
3.2.4.4.3	Solid-State NMR Characterization of the Accessibility and Strength of Brønsted Acid Sites by Probe Molecules	1168	3.3.1.4.2	Determination of the Adsorption Isotherm	1221
3.2.4.4.4	Solid-State NMR Investigations of Lewis Acid Sites by Probe Molecules	1174	3.3.1.5	Evaluation of Adsorption Data	1222
3.2.4.4.5	Solid-State NMR Investigations of Base Sites in Solid Catalysts	1175	3.3.1.5.1	Presentation of Primary Data	1222
	References	1176	3.3.1.5.2	Classification of Adsorption Isotherms	1222
3.2.5	Active Phase–Support Interactions	1178	3.3.1.5.3	Adsorption Hysteresis	1223
	<i>Agnieszka M. Ruppert and Bert M. Weckhuysen</i>		3.3.1.6	Determination of Surface Area	1224
3.2.5.1	Metal–Support Interactions	1178	3.3.1.6.1	Application of the BET Method	1224
	References	1187	3.3.1.6.2	Empirical Procedures for Isotherm Analysis	1225
3.2.5.2	Oxide–Support Interactions	1188	3.3.1.7	Assessment of Mesoporosity	1226
	<i>Jaap A. Bergwerff and Bert M. Weckhuysen</i>		3.3.1.7.1	Properties of Porous Materials	1226
	References	1196	3.3.1.7.2	Application of the Kelvin Equation	1226
3.2.6	Carbonaceous Deposits	1197	3.3.1.7.3	Computation of Mesopore Size Distribution	1226
	<i>Peter W. Albers and Jens Weitkamp</i>		3.3.1.8	Assessment of Microporosity	1227
3.2.6.1	Introduction	1197	3.3.1.8.1	Terminology	1227
3.2.6.2	Formation and Chemical Nature of Carbonaceous Deposits	1198	3.3.1.8.2	Concept of Surface Area	1227
3.2.6.3	Educt Molecules and Alkaline Elements	1206	3.3.1.8.3	Assessment of Micropore Volume	1228
3.2.6.4	Coke Distribution, Porosity and Pore Blocking	1206	3.3.1.9	General Conclusions and Recommendations	1228
3.2.6.5	Graphiticity	1208		References	1229
			3.3.2	Methods and Procedures for Catalyst Characterization	1230
				<i>Jerzy Haber, Jochen H. Block, and Bernard Delmon</i>	
			3.3.2.1	Introduction	1230
			3.3.2.2	Catalyst Preparation	1230
			3.3.2.2.1	Preparation of the Primary Solid	1230

3.3.2.2.2	Treatment of Intermediate Solids or Precursors	1234	3.3.2.4.6	Vibrational Spectroscopies	1244
3.3.2.2.3	Activation of the Precursor	1234	3.3.2.4.7	Electron Spectroscopies	1244
3.3.2.2.4	Forming Methods	1235	3.3.2.4.8	Determination of Spatial Distribution of Elements	1245
3.3.2.2.5	Stability During Handling and Storage	1236	3.3.2.4.9	Secondary Ion Mass Spectroscopy (SIMS)	1246
3.3.2.3	Characterization of Surface Properties by Adsorption Methods	1236	3.3.2.4.10	Ion Beam Techniques	1246
3.3.2.3.1	Methodology	1237	3.3.2.4.11	Depth Profiling	1246
3.3.2.3.2	Categories of Catalysts	1238	3.3.2.5	Catalytic Properties	1246
3.3.2.4	Fine Structure of Catalysts	1240	3.3.2.5.1	Reactor Types and Measurement Methods	1246
3.3.2.4.1	Surface Structure and Chemical Composition	1240	3.3.2.5.2	Kinetic Analysis	1250
3.3.2.4.2	Surface Structure and Topography	1240	3.3.2.5.3	Inhibition of Catalytic Action	1253
3.3.2.4.3	X-Ray and Neutron Methods for Structure Determination	1241	3.3.2.5.4	Deactivation of Catalysts and Time-Dependent Effects	1255
3.3.2.4.4	Ion Scattering Techniques	1242	3.3.2.5.5	Regeneration	1256
3.3.2.4.5	Electron State and Local Environment of Elements	1243		References	1257