

CONTENTS

OF VOLUME 1, PART II

PREFACE TO VOLUME 1	v
CONTRIBUTORS TO VOLUME 1, PARTS I AND II	vii
CONTENTS OF VOLUME 1, PART I	xvii

6. DISPOSAL OR USE OF GYPSUM 503

I. Disposal as Waste Material	505
A. U.S. Practice	505
<i>Quentin D. Bowers</i>	
References	510
B. European Practice	511
<i>Hans Beijer and Willem Mak</i>	
Reference	517
II. By-product Recovery	519
A. As Raw Material for Plaster and Cement—Japanese Practice	519
<i>Keiichi Murakami and Shoichiro Hori</i>	
References	529
B. As Raw Material for Plaster and Cement—European Practice	531
<i>C. W. Scaife and D. Kitchen</i>	
References	540
C. In Production of Ammonium Sulfate	541
<i>N. D. Gopinath</i>	
References	565
D. In Production of Sulfuric Acid	567
<i>J. M. Stinson</i>	
References	577

7. CONCENTRATION OF WET-PROCESS ACID 579

I. Direct Contact Evaporation	581
<i>J. H. Forster</i>	
A. Introduction	581

B. Hot Gas Evaporation	582
C. Submerged Combustion Evaporation	588
References	605
II. Tube-Type Evaporators	607
<i>C. W. Putnam and E. W. Taylor</i>	
A. Chemistry	607
B. Production and Design Factors	612
C. Development of Evaporators	619
D. Current Types and Their Performance	621
E. Future Trends and Developments	625
References	626
III. Evaporator-Crystallizer	627
<i>S. A. Laurich and Hans Svanoe</i>	
References	634

8. PURIFICATION OF WET-PROCESS ACID 635

I. Nature of Impurities	637
<i>J. R. Lehr</i>	
A. Introduction	637
B. Nature of Precipitated Impurities	639
C. Methods for Characterizing Impurities	654
D. Nature of Dissolved Impurities	657
E. Nature of Impurities Derived from Phosphate Rock	657
F. Conclusions	668
G. Appendix: X-Ray Diffraction Pattern Data	684
References	684
II. Removal of Impurities	687
A. U.S. Practice	687
<i>L. B. Hein</i>	
References	708
B. Solvent Extraction: Chloride Addition and Temperature Cycling	709
<i>A. Baniel and R. Blumberg</i>	
References	719
C. Solvent Extraction: Use of Partially Immiscible Solvent	721
<i>A. V. Slack</i>	
Reference	724

9. HANDLING AND TREATMENT OF PLANT EFFLUENTS 725

I.	Pollution Problems in Phosphoric Acid Production	727
	<i>K. K. Huffstutler</i>	
	A. Pollution of Surface Water	727
	B. Atmospheric Pollution	731
	References	739
II.	Scrubbing of Gaseous Effluents	741
	<i>A. J. Teller and David Reeve</i>	
	A. Sources of Fluorine-Containing Effluents	742
	B. Factors in Scrubbing Gaseous Effluents from Fertilizer Plants	751
	C. Pollution Abatement Systems	753
	References	763
III.	Recovery of Fluorides as By-products	765
	<i>M. D. Sanders</i>	
	A. Reactor Slurry Vapors	766
	B. Recovery of Fluosilicates from Filter Acid	767
	C. Vacuum Concentrator Vapors	768
	D. Uses for By-product Fluorides	775
	E. Conclusions	777
	References	777

10. CORROSION AND MATERIALS OF CONSTRUCTION 779*Enrico Pelitti*

I.	General Considerations—Materials and Processes	781
	A. Manufacturing Processes	781
	B. Materials To Be Handled	782
	C. Ambient Conditions and Other Considerations	806
	D. Economics of Material Selection	808
II.	Corrosion	810
	A. Nature and Types of Corrosion and Attack	810
	B. Factors Influencing Corrosion and Attack	815
	C. Corrosion Testing and Protection	818
III.	Materials of Construction	823
	A. Ferrous Metals	824
	B. High-Nickel Alloys	833
	C. Nonferrous Metals	840
	D. Elastomers	843
	E. Plastics	852
	F. Miscellaneous Materials	865

IV. Materials Reviewed in This Chapter	884
References	884
11. USE OF ACIDS OTHER THAN SULFURIC ACID	887
I. Hydrochloric Acid	889
<i>A. Baniel and R. Blumberg</i>	
A. Introduction	889
B. Dissolution	902
C. Liquid-Liquid Contacting	905
D. Distillation Operations	908
E. Materials of Construction	909
F. Cost Considerations	910
References	911
II. Nitric Acid	913
<i>R. J. Piepers</i>	
A. Principles of the Nitric Acid Process	914
B. Removal of Calcium by Crystallization of $\text{Ca}(\text{NO}_3)_2 \cdot 4\text{H}_2\text{O}$	915
C. Alternative Methods of Calcium Removal	923
References	925
12. PHOSPHORIC ACID BY THE FURNACE PROCESS	927
<i>Gerhard Hartlapp</i>	
I. Systematization of the Phosphoric Acids	929
II. Physical and Chemical Properties	931
III. Historical Development	934
A. Electric-Furnace Process	934
B. Blast-Furnace Process	943
IV. Raw Materials	944
A. Phosphate Rock	944
B. Silica and Coke	946
V. Plant Location	946
VI. Phosphorus Production	948
VII. Phosphorus Feeding and Metering	960
VIII. Combustion and Hydration in Separate Vessels	961
IX. Combustion and Hydration in the Same Vessel	963
X. Recovery of P_2O_5 from Waste Gas	966
XI. Special Production Techniques	970
A. Removal of Arsenic	970
B. Chemically Pure Phosphoric Acid and Crystallized Phosphoric Acid	971

C. Production of Sodium Phosphate Solution in the Combustion Tower	973
D. Dry Phosphorus Pentoxide	974
E. Recovery of Heat or By-products	975
XII. Waste Water Problems	977
References	980
 13. POLYPHOSPHORIC ACID	 983
I. Chemistry	985
<i>R. F. Jameson</i>	
A. Nomenclature	987
B. Analysis of Condensed Phosphates	988
C. Structure of Condensed Phosphoric Acids	991
D. Reorganization Theory	995
E. Ionization of Acids	997
F. Hydrolysis of Acids	998
G. Complex Formation by Condensed Phosphate Anions	1001
References	1004
II. Production by Furnace Method	1007
<i>M. M. Striplin, Jr.</i>	
A. Methods of Producing Furnace Acid	1010
B. Optimum-Type Plant for Fertilizer Industry	1014
C. Design of TVA Unlined Stainless Steel Acid Plant	1017
D. Performance of TVA Plant	1048
References	1060
III. Production by Wet Process	1061
A. Direct Heating	1061
<i>W. C. Scott, Jr.</i>	
References	1081
B. Use of Heat-Transfer Surfaces	1083
<i>R. A. Shetler and J. M. Williams</i>	
References	1101
 14. HANDLING AND SHIPPING PHOSPHORIC ACID	 1103
<i>A. W. Petersen</i>	
I. Orthophosphoric Acid (52-62% P_2O_5)	1104
A. Properties that Affect Handling	1104
B. Storage	1109
C. Handling	1110

D. Shipping	1113
E. Sludge	1118
II. Superphosphoric Acid (63–85% P_2O_5)	1121
A. Properties That Affect Handling	1121
B. Storage	1127
C. Shipping and Handling	1128
References	1131
AUTHOR INDEX	1133
SUBJECT INDEX	1145