
CONTENTS

<i>Preface</i>	xi
<i>List of Selected Books and Periodicals</i>	xv
Chapter 1 Introduction	1
Chapter 2 Basic Concepts	7
2-1 Introduction	7
2-2 Definition of Terms	7
2-3 Calibration	8
2-4 Standards	9
2-5 Dimensions and Units	12
2-6 The Generalized Measurement System	17
2-7 Basic Concepts in Dynamic Measurements	19
2-8 System Response	23
2-9 Distortion	25
2-10 Impedance Matching	25
2-11 Experiment Planning	28
2-12 Report Writing	33
Chapter 3 Analysis of Experimental Data	41
3-1 Introduction	41
3-2 Causes and Types of Experimental Errors	42
3-3 Error Analysis on a Commonsense Basis	43
3-4 Uncertainty Analysis	44
3-5 Statistical Analysis of Experimental Data	51
3-6 Probability Distributions	55
3-7 The Gaussian or Normal Error Distribution	59
3-8 Probability Graph Paper	67
3-9 The Chi-Square Test of Goodness of Fit	69
3-10 Method of Least Squares	74

3-11	Standard Deviation of the Mean	77
3-12	Graphical Analysis and Curve Fitting	79
3-13	General Considerations in Data Analysis	82
Chapter 4 Basic Electrical Measurements and Sensing Devices		89
4-1	Introduction	89
4-2	Forces of Electromagnetic Origin	89
4-3	Waveform Measures	94
4-4	Basic Analog Meters	96
4-5	Basic Digital Meters	102
4-6	Basic Input Circuits	104
4-7	Amplifiers	117
4-8	Power Supplies	127
4-9	Signal Conditioning	129
4-10	The Vacuum Tube Voltmeter (VTVM)	137
4-11	Digital Voltmeters	139
4-12	The Oscilloscope	141
4-13	Sampling Oscilloscopes	145
4-14	Oscillographs	146
4-15	Counters—Time and Frequency Measurements	149
4-16	Transducers	151
4-17	The Variable-Resistance Transducer	151
4-18	The Differential Transformer (LVDT)	153
4-19	Capacitive Transducers	156
4-20	Piezoelectric Transducers	158
4-21	Photoelectric Effects	159
4-22	Photoconductive Transducers	160
4-23	Photovoltaic Cells	163
4-24	Ionization Transducers	163
4-25	Magnetometer Search Coil	164
4-26	Hall-Effect Transducers	165
4-27	Summary	167
Chapter 5 Displacement and Area Measurements		173
5-1	Introduction	173
5-2	Dimensional Measurements	173
5-3	Gage Blocks	175
5-4	Optical Methods	176
5-5	Pneumatic Displacement Gage	179
5-6	Area Measurements	181
5-7	The Planimeter	181
5-8	Graphical and Numerical Methods for Area Measurement	184
5-9	Surface Areas	185
Chapter 6 Pressure Measurement		189
6-1	Introduction	189
6-2	Dynamic Response Considerations	191
6-3	Mechanical Pressure-Measurement Devices	194

6-4	Dead-Weight Tester	196
6-5	Bourdon-Tube Pressure Gage	197
6-6	Diaphragm and Bellows Gages	198
6-7	The Bridgman Gage	202
6-8	Low-Pressure Measurement	202
6-9	The McLeod Gage	202
6-10	Pirani Thermal-Conductivity Gage	204
6-11	The Knudsen Gage	205
6-12	The Ionization Gage	207
6-13	The Alphatron	207
6-14	Summary	208
Chapter 7 Flow Measurement		213
7-1	Introduction	213
7-2	Positive-Displacement Methods	214
7-3	Flow-Obstruction Methods	216
7-4	Practical Considerations for Obstruction Meters	220
7-5	The Sonic Nozzle	229
7-6	Flow Measurement by Drag Effects	231
7-7	Hot-Wire and Hot-Film Anemometers	235
7-8	Magnetic Flowmeters	239
7-9	Flow-Visualization Methods	240
7-10	The Shadowgraph	242
7-11	The Schlieren	244
7-12	The Interferometer	246
7-13	The Laser Doppler Anemometer (LDA)	249
7-14	Smoke Methods	252
7-15	Pressure Probes	253
7-16	Impact Pressure in Supersonic Flow	258
7-17	Summary	259
Chapter 8 The Measurement of Temperature		267
8-1	Introduction	267
8-2	Temperature Scales	267
8-3	The Ideal-Gas Thermometer	268
8-4	Temperature Measurement by Mechanical Effects	270
8-5	Temperature Measurement by Electrical Effects	273
8-6	Temperature Measurement by Radiation	288
8-7	Effect of Heat Transfer on Temperature Measurement	294
8-8	Transient Response of Thermal Systems	304
8-9	Thermocouple Compensation	307
8-10	Temperature Measurements in High-Speed Flow	310
8-11	Summary	314
Chapter 9 Thermal- and Transport-Property Measurements		319
9-1	Introduction	319
9-2	Thermal-Conductivity Measurements	320
9-3	Thermal Conductivity of Liquids and Gases	324

9-4	Measurement of Viscosity	326
9-5	Gas Diffusion	332
9-6	Calorimetry	335
9-7	Convection Heat-Transfer Measurements	339
9-8	Humidity Measurements	342
9-9	Heat-Flux Meters	345
Chapter 10 Force, Torque, and Strain Measurements		353
10-1	Introduction	353
10-2	Mass Balance Measurements	354
10-3	Elastic Elements for Force Measurements	357
10-4	Torque Measurements	360
10-5	Stress and Strain	362
10-6	Strain Measurements	364
10-7	Electrical-Resistance Strain Gages	365
10-8	Measurement of Resistance Strain-Gage Outputs	368
10-9	Temperature Compensation	370
10-10	Strain-Gage Rosettes	371
10-11	The Unbonded Resistance Strain Gage	374
Chapter 11 Motion and Vibration Measurement		379
11-1	Introduction	379
11-2	Two Simple Vibration Instruments	379
11-3	Principles of the Seismic Instrument	381
11-4	Practical Considerations for Seismic Instruments	387
11-5	Sound Measurements	390
Chapter 12 Thermal- and Nuclear-Radiation Measurements		405
12-1	Introduction	405
12-2	Detection of Thermal Radiation	405
12-3	Measurement of Emissivity	410
12-4	Reflectivity and Transmissivity Measurements	412
12-5	Solar Radiation Measurements	414
12-6	Nuclear Radiation	416
12-7	Detection of Nuclear Radiation	416
12-8	The Geiger-Müller Counter	416
12-9	Ionization Chambers	418
12-10	Photographic-Detection Methods	419
12-11	The Scintillation Counter	419
12-12	Neutron Detection	420
12-13	Statistics of Counting	421
Chapter 13 Air-Pollution Sampling and Measurement		429
13-1	Introduction	429
13-2	Units for Pollution Measurement	429
13-3	Air-Pollution Standards	430
13-4	General Air-Sampling Train	433

13-5	Gas Sampling Techniques	434
13-6	Particulate Sampling Techniques	435
13-7	Sulfur Dioxide Measurements	444
13-8	Combustion Products Measurements	447
13-9	Opacity Measurements	451
13-10	Odor Measurement	452
Chapter 14 Data Acquisition and Processing		457
14-1	Introduction	457
14-2	The General Data-Acquisition System	457
14-3	Signal Conditioning Revisited	460
14-4	Data Transmission	463
14-5	Analog-to-Digital and Digital-to-Analog Conversion	465
14-6	Data Storage and Display	468
14-7	The Program as a Substitute for Wired Logic	469
14-8	Summary	473
<i>Appendix</i>		475
<i>Index</i>		587