

# Contents

---

<b>Chapter 1</b>	<b>Introduction</b>	<b>1</b>
1–1	Strategy of Experimentation	1
1–2	Some Typical Applications of Experimental Design	8
1–3	Basic Principles	12
1–4	Guidelines for Designing Experiments	14
1–5	A Brief History of Statistical Design	19
1–6	Summary: Using Statistical Techniques in Experimentation	21
1–7	Problems	22
<b>Chapter 2</b>	<b>Simple Comparative Experiments</b>	<b>23</b>
2–1	Introduction	23
2–2	Basic Statistical Concepts	24
2–3	Sampling and Sampling Distributions	28
2–4	Inferences about the Differences in Means, Randomized Designs	34
2–4.1	Hypothesis Testing	34
2–4.2	Choice of Sample Size	41
2–4.3	Confidence Intervals	43
2–4.4	The Case Where $\sigma_1^2 \neq \sigma_2^2$	45
2–4.5	The Case Where $\sigma_1^2$ and $\sigma_2^2$ Are Known	45
2–4.6	Comparing a Single Mean to a Specified Value	46
2–4.7	Summary	47
2–5	Inferences about the Differences in Means, Paired Comparison Designs	48
2–5.1	The Paired Comparison Problem	48
2–5.2	Advantages of the Paired Comparison Design	51
2–6	Inferences about the Variances of Normal Distributions	52
2–7	Problems	54
<b>Chapter 3</b>	<b>Experiments with a Single Factor: The Analysis of Variance</b>	<b>60</b>
3–1	An Example	61
3–2	The Analysis of Variance	63
3–3	Analysis of the Fixed Effects Model	65
3–3.1	Decomposition of the Total Sum of Squares	66
3–3.2	Statistical Analysis	68
3–3.3	Estimation of the Model Parameters	73
3–3.4	Unbalanced Data	75
3–4	Model Adequacy Checking	75
3–4.1	The Normality Assumption	76
3–4.2	Plot of Residuals in Time Sequence	78

3–4.3	Plot of Residuals Versus Fitted Values	79
3–4.4	Plots of Residuals Versus Other Variables	84
3–5	Practical Interpretation of Results	85
3–5.1	A Regression Model	85
3–5.2	Comparisons Among Treatment Means	87
3–5.3	Graphical Comparisons of Means	87
3–5.4	Contrasts	88
3–5.5	Orthogonal Contrasts	91
3–5.6	Scheffé’s Method for Comparing All Contrasts	93
3–5.7	Comparing Pairs of Treatment Means	94
3–5.8	Comparing Treatment Means with a Control	97
3–6	Sample Computer Output	98
3–7	Determining Sample Size	101
3–7.1	Operating Characteristic Curves	101
3–7.2	Specifying a Standard Deviation Increase	104
3–7.3	Confidence Interval Estimation Method	104
3–8	Discovering Dispersion Effects	105
3–9	The Regression Approach to the Analysis of Variance	107
3–9.1	Least Squares Estimation of the Model Parameters	107
3–9.2	The General Regression Significance Test	108
3–10	Nonparametric Methods in the Analysis of Variance	110
3–10.1	The Kruskal–Wallis Test	110
3–10.2	General Comments on the Rank Transformation	112
3–11	Problems	112
<b>Chapter 4</b>	<b>Randomized Blocks, Latin Squares, and Related Designs</b>	<b>119</b>
4–1	The Randomized Complete Block Design	119
4–1.1	Statistical Analysis of the RCBD	121
4–1.2	Model Adequacy Checking	128
4–1.3	Some Other Aspects of the Randomized Complete Block Design	130
4–1.4	Estimating Model Parameters and the General Regression Significance Test	133
4–2	The Latin Square Design	136
4–3	The Graeco-Latin Square Design	142
4–4	Balanced Incomplete Block Designs	145
4–4.1	Statistical Analysis of the BIBD	146
4–4.2	Least Squares Estimation of the Parameters	150
4–4.3	Recovery of Interblock Information in the BIBD	152
4–5	Problems	154
<b>Chapter 5</b>	<b>Introduction to Factorial Designs</b>	<b>160</b>
5–1	Basic Definitions and Principles	160
5–2	The Advantage of Factorials	163

5–3	The Two-Factor Factorial Design	164
5–3.1	An Example	164
5–3.2	Statistical Analysis of the Fixed Effects Model	167
5–3.3	Model Adequacy Checking	172
5–3.4	Estimating the Model Parameters	175
5–3.5	Choice of Sample Size	177
5–3.6	The Assumption of No Interaction in a Two-Factor Model	178
5–3.7	One Observation per Cell	179
5–4	The General Factorial Design	182
5–5	Fitting Response Curves and Surfaces	188
5–6	Blocking in a Factorial Design	193
5–7	Problems	197
<b>Chapter 6 The <math>2^k</math> Factorial Design</b>		<b>203</b>
6–1	Introduction	203
6–2	The $2^2$ Design	204
6–3	The $2^3$ Design	211
6–4	The General $2^k$ Design	224
6–5	A Single Replicate of the $2^k$ Design	226
6–6	The Addition of Center Points to the $2^k$ Design	247
6–7	Why We Work with Coded Design Variables	251
6–8	Problems	254
<b>Chapter 7 Blocking and Confounding in the <math>2^k</math> Factorial Design</b>		<b>265</b>
7–1	Introduction	265
7–2	Blocking a Replicated $2^k$ Factorial Design	266
7–3	Confounding in the $2^k$ Factorial Design	266
7–4	Confounding the $2^k$ Factorial Design in Two Blocks	267
7–5	Another Illustration of Why Blocking Is Important	273
7–6	Confounding the $2^k$ Factorial Design in Four Blocks	275
7–7	Confounding the $2^k$ Factorial Design in $2^p$ Blocks	276
7–8	Partial Confounding	278
7–9	Problems	280
<b>Chapter 8 Two-Level Fractional Factorial Designs</b>		<b>282</b>
8–1	Introduction	282
8–2	The One-Half Fraction of the $2^k$ Design	283
8–2.1	Definitions and Basic Principles	283
8–2.2	Design Resolution	285
8–2.3	Construction and Analysis of the One-Half Fraction	286
8–3	The One-Quarter Fraction of the $2^k$ Design	296

8–4	The General $2^{k-p}$ Fractional Factorial Design	303
8–4.1	Choosing a Design	303
8–4.2	Analysis of $2^{k-p}$ Fractional Factorials	306
8–4.3	Blocking Fractional Factorials	307
8–5	Resolution III Designs	312
8–5.1	Constructing Resolution III Designs	312
8–5.2	Fold Over of Resolution III Fractions to Separate Aliased Effects	314
8–5.3	Plackett–Burman Designs	319
8–6	Resolution IV and V Designs	322
8–6.1	Resolution IV Designs	322
8–6.2	Sequential Experimentation with Resolution IV Designs	325
8–6.3	Resolution V Designs	331
8–7	Supersaturated Designs	333
8–8	Summary	335
8–9	Problems	335
<b>Chapter 9</b>	<b>Three-Level and Mixed-Level Factorial and Fractional Factorial Designs</b>	<b>347</b>
9–1	The $3^k$ Factorial Design	347
9–1.1	Notation and Motivation for the $3^k$ Design	347
9–1.2	The $3^2$ Design	349
9–1.3	The $3^3$ Design	351
9–1.4	The General $3^k$ Design	355
9–2	Confounding in the $3^k$ Factorial Design	356
9–2.1	The $3^k$ Factorial Design in Three Blocks	356
9–2.2	The $3^k$ Factorial Design in Nine Blocks	360
9–2.3	The $3^k$ Factorial Design in $3^p$ Blocks	360
9–3	Fractional Replication of the $3^k$ Factorial Design	361
9–3.1	The One-Third Fraction of the $3^k$ Factorial Design	361
9–3.2	Other $3^{k-p}$ Fractional Factorial Designs	364
9–4	Factorials with Mixed Levels	365
9–4.1	Factors at Two and Three Levels	366
9–4.2	Factors at Two and Four Levels	367
9–5	Problems	369
<b>Chapter 10</b>	<b>Fitting Regression Models</b>	<b>373</b>
10–1	Introduction	373
10–2	Linear Regression Models	374
10–3	Estimation of the Parameters in Linear Regression Models	375
10–4	Hypothesis Testing in Multiple Regression	388
10–4.1	Test for Significance of Regression	388
10–4.2	Tests on Individual Regression Coefficients and Groups of Coefficients	390

10–5	Confidence Intervals in Multiple Regression	393
10–5.1	Confidence Intervals on the Individual Regression Coefficients	393
10–5.2	Confidence Interval on the Mean Response	394
10–6	Prediction of New Response Observations	394
10–7	Regression Model Diagnostics	396
10–7.1	Scaled Residuals and PRESS	396
10–7.2	Influence Diagnostics	399
10–8	Testing for Lack of Fit	400
10–9	Problems	401
<b>Chapter 11 Response Surface Methods and Designs</b>		<b>405</b>
11–1	Introduction to Response Surface Methodology	405
11–2	The Method of Steepest Ascent	407
11–3	Analysis of a Second-Order Response Surface	413
11–3.1	Location of the Stationary Point	413
11–3.2	Characterizing the Response Surface	415
11–3.3	Ridge Systems	422
11–3.4	Multiple Responses	423
11–4	Experimental Designs for Fitting Response Surfaces	427
11–4.1	Designs for Fitting the First-Order Model	428
11–4.2	Designs for Fitting the Second-Order Model	428
11–4.3	Blocking in Response Surface Designs	436
11–4.4	Computer-Generated (Optimal) Designs	439
11–5	Mixture Experiments	444
11–6	Evolutionary Operation	452
11–7	Problems	458
<b>Chapter 12 Robust Parameter Design and Process Robustness Studies</b>		<b>464</b>
12–1	Introduction	464
12–2	Crossed Array Designs	466
12–3	Analysis of the Crossed Array Design	468
12–4	Combined Array Designs and the Response Model Approach	471
12–5	Choice of Designs	477
12–6	Problems	480
<b>Chapter 13 Experiments with Random Factors</b>		<b>484</b>
13–1	The Random Effects Model	485
13–2	The Two-Factor Factorial with Random Factors	490
13–3	The Two-Factor Mixed Model	495
13–4	Sample Size Determination with Random Effects	500
13–5	Rules for Expected Mean Squares	501
13–6	Approximate <i>F</i> Tests	505

13–7	Some Additional Topics on Estimation of Variance Components	511
13–7.1	Approximate Confidence Intervals on Variance Components	511
13–7.2	The Modified Large-Sample Method	514
13–7.3	Maximum Likelihood Estimation of Variance Components	516
13–8	Problems	521
<b>Chapter 14 Nested and Split-Plot Designs</b>		<b>525</b>
14–1	The Two-Stage Nested Design	525
14–1.1	Statistical Analysis	526
14–1.2	Diagnostic Checking	531
14–1.3	Variance Components	532
14–1.4	Staggered Nested Designs	533
14–2	The General $m$ -Stage Nested Design	534
14–3	Designs with Both Nested and Factorial Factors	536
14–4	The Split-Plot Design	540
14–5	Other Variations of the Split-Plot Design	545
14–5.1	Split-Plot Designs with More Than Two Factors	545
14–5.2	The Split-Split-Plot Design	550
14–5.3	The Strip-Split-Plot Design	552
14–6	Problems	554
<b>Chapter 15 Other Design and Analysis Topics</b>		<b>559</b>
15–1	Nonnormal Responses and Transformations	560
15–1.1	Selecting a Transformation: The Box–Cox Method	560
15–1.2	The Generalized Linear Model	563
15–2	Unbalanced Data in a Factorial Design	570
15–2.1	Proportional Data: An Easy Case	571
15–2.2	Approximate Methods	572
15–2.3	The Exact Method	574
15–3	The Analysis of Covariance	574
15–3.1	Description of the Procedure	576
15–3.2	Computer Solution	583
15–3.3	Development by the General Regression Significance Test	584
15–3.4	Factorial Experiments with Covariates	586
15–4	Repeated Measures	590
15–5	Problems	592
<b>Bibliography</b>		<b>595</b>
<b>Appendix</b>		<b>603</b>
<b>Table I.</b>	Cumulative Standard Normal Distribution	604
<b>Table II.</b>	Percentage Points of the $t$ Distribution	606
<b>Table III.</b>	Percentage Points of the $\chi^2$ Distribution	607
<b>Table IV.</b>	Percentage Points of the $F$ Distribution	608

<b>Table V.</b>	Operating Characteristic Curves for the Fixed Effects Model Analysis of Variance	613
<b>Table VI.</b>	Operating Characteristic Curves for the Random Effects Model Analysis of Variance	617
<b>Table VII.</b>	Percentage Points of the Studentized Range Statistic	621
<b>Table VIII.</b>	Critical Values for Dunnett's Test for Comparing Treatments with a Control	623
<b>Table IX.</b>	Coefficients of Orthogonal Polynomials	625
<b>Table X.</b>	Alias Relationships for $2^{k-p}$ Fractional Factorial Designs with $k \leq 15$ and $n \leq 64$	626
<b>Index</b>		<b>638</b>