

Contents

Preface	xiii
Acknowledgements	xvii
Abbreviations	xix
Symbols	xxi
Nomenclature	xxiii
Introduction	xxv
PART I FUNDAMENTALS OF MULTIVARIATE STATISTICAL PROCESS CONTROL	1
1 Motivation for multivariate statistical process control	3
1.1 Summary of statistical process control	3
1.1.1 Roots and evolution of statistical process control	4
1.1.2 Principles of statistical process control	5
1.1.3 Hypothesis testing, Type I and II errors	12
1.2 Why multivariate statistical process control	15
1.2.1 Statistically uncorrelated variables	16
1.2.2 Perfectly correlated variables	17
1.2.3 Highly correlated variables	19
1.2.4 Type I and II errors and dimension reduction	24
1.3 Tutorial session	26
2 Multivariate data modeling methods	28
2.1 Principal component analysis	30
2.1.1 Assumptions for underlying data structure	30
2.1.2 Geometric analysis of data structure	33
2.1.3 A simulation example	34
2.2 Partial least squares	38
2.2.1 Assumptions for underlying data structure	39

2.2.2	Deflation procedure for estimating data models	41
2.2.3	A simulation example	43
2.3	Maximum redundancy partial least squares	49
2.3.1	Assumptions for underlying data structure	49
2.3.2	Source signal estimation	50
2.3.3	Geometric analysis of data structure	52
2.3.4	A simulation example	58
2.4	Estimating the number of source signals	65
2.4.1	Stopping rules for PCA models	65
2.4.2	Stopping rules for PLS models	76
2.5	Tutorial Session	79
3	Process monitoring charts	81
3.1	Fault detection	83
3.1.1	Scatter diagrams	84
3.1.2	Non-negative quadratic monitoring statistics	85
3.2	Fault isolation and identification	93
3.2.1	Contribution charts	95
3.2.2	Residual-based tests	98
3.2.3	Variable reconstruction	100
3.3	Geometry of variable projections	111
3.3.1	Linear dependency of projection residuals	111
3.3.2	Geometric analysis of variable reconstruction	112
3.4	Tutorial session	119
PART II	APPLICATION STUDIES	121
4	Application to a chemical reaction process	123
4.1	Process description	123
4.2	Identification of a monitoring model	124
4.3	Diagnosis of a fault condition	133
5	Application to a distillation process	141
5.1	Process description	141
5.2	Identification of a monitoring model	144
5.3	Diagnosis of a fault condition	153
PART III	ADVANCES IN MULTIVARIATE STATISTICAL PROCESS CONTROL	165
6	Further modeling issues	167
6.1	Accuracy of estimating PCA models	168
6.1.1	Revisiting the eigendecomposition of $S_{z_0 z_0}$	168

6.1.2	Two illustrative examples	171
6.1.3	Maximum likelihood PCA for known S_{gg}	172
6.1.4	Maximum likelihood PCA for unknown S_{gg}	177
6.1.5	A simulation example	182
6.1.6	A stopping rule for maximum likelihood PCA models	187
6.1.7	Properties of model and residual subspace estimates	189
6.1.8	Application to a chemical reaction process – revisited	194
6.2	Accuracy of estimating PLS models	202
6.2.1	Bias and variance of parameter estimation	203
6.2.2	Comparing accuracy of PLS and OLS regression models	205
6.2.3	Impact of error-in-variables structure upon PLS models	212
6.2.4	Error-in-variable estimate for known S_{ee}	218
6.2.5	Error-in-variable estimate for unknown S_{ee}	219
6.2.6	Application to a distillation process – revisited	223
6.3	Robust model estimation	226
6.3.1	Robust parameter estimation	228
6.3.2	Trimming approaches	231
6.4	Small sample sets	232
6.5	Tutorial session	237
7	Monitoring multivariate time-varying processes	240
7.1	Problem analysis	241
7.2	Recursive principal component analysis	242
7.3	Moving window principal component analysis	244
7.3.1	Adapting the data correlation matrix	244
7.3.2	Adapting the eigendecomposition	247
7.3.3	Computational analysis of the adaptation procedure	251
7.3.4	Adaptation of control limits	252
7.3.5	Process monitoring using an application delay	253
7.3.6	Minimum window length	254
7.4	A simulation example	257
7.4.1	Data generation	257
7.4.2	Application of PCA	258
7.4.3	Utilizing MWPCA based on an application delay	261
7.5	Application to a Fluid Catalytic Cracking Unit	265
7.5.1	Process description	266
7.5.2	Data generation	268
7.5.3	Pre-analysis of simulated data	272
7.5.4	Application of PCA	273
7.5.5	Application of MWPCA	275
7.6	Application to a furnace process	278
7.6.1	Process description	278
7.6.2	Description of sensor bias	279
7.6.3	Application of PCA	280
7.6.4	Utilizing MWPCA based on an application delay	282

7.7	Adaptive partial least squares	286
7.7.1	Recursive adaptation of S_{x_0, x_0} and S_{x_0, y_0}	287
7.7.2	Moving window adaptation of S_{x_0, x_0} and S_{x_0, y_0}	287
7.7.3	Adapting the number of source signals	287
7.7.4	Adaptation of the PLS model	290
7.8	Tutorial Session	292
8	Monitoring changes in covariance structure	293
8.1	Problem analysis	294
8.1.1	First intuitive example	294
8.1.2	Generic statistical analysis	297
8.1.3	Second intuitive example	299
8.2	Preliminary discussion of related techniques	304
8.3	Definition of primary and improved residuals	305
8.3.1	Primary residuals for eigenvectors	306
8.3.2	Primary residuals for eigenvalues	307
8.3.3	Comparing both types of primary residuals	307
8.3.4	Statistical properties of primary residuals	312
8.3.5	Improved residuals for eigenvalues	315
8.4	Revisiting the simulation examples of Section 8.1	317
8.4.1	First simulation example	318
8.4.2	Second simulation example	321
8.5	Fault isolation and identification	324
8.5.1	Diagnosis of step-type fault conditions	325
8.5.2	Diagnosis of general deterministic fault conditions	328
8.5.3	A simulation example	328
8.6	Application study of a gearbox system	331
8.6.1	Process description	332
8.6.2	Fault description	332
8.6.3	Identification of a monitoring model	334
8.6.4	Detecting a fault condition	338
8.7	Analysis of primary and improved residuals	341
8.7.1	Central limit theorem	341
8.7.2	Further statistical properties of primary residuals	344
8.7.3	Sensitivity of statistics based on improved residuals	349
8.8	Tutorial session	353
PART IV	DESCRIPTION OF MODELING METHODS	355
9	Principal component analysis	357
9.1	The core algorithm	357
9.2	Summary of the PCA algorithm	362
9.3	Properties of a PCA model	363

10 Partial least squares	375
10.1 Preliminaries	375
10.2 The core algorithm	377
10.3 Summary of the PLS algorithm	380
10.4 Properties of PLS	381
10.5 Properties of maximum redundancy PLS	396
References	410
Index	427