

Contents

Page

Foreword	iv
Introduction.....	v
1 Scope	1
2 Normative references	1
3 Terms and definitions	2
3.1 General definitions	2
3.2 Sampling definitions	3
3.3 Welding terms	5
3.4 Statistical terms	7
4 Principle	8
5 Requirement.....	9
6 Equipment	9
6.1 Sampling equipment	9
6.2 Weighing equipment, if required	10
7 Assessment strategy	11
8 Measurement strategy	11
8.1 General	11
8.2 Personal exposure measurement.....	11
8.3 Fixed-point measurements.....	11
8.4 Selection of measurement conditions and measurement pattern	12
9 Procedure	13
9.1 Preliminary considerations	13
9.2 Preparation for sampling	14
9.3 Sampling position	15
9.4 Sampling	15
9.5 Transportation	16
9.6 Analysis	16
9.7 Expression of results	17
10 Exposure assessment.....	18
11 Recording of sampling data and presentation of results.....	18
Annex A (normative) Gravimetric analysis	19
Annex B (informative) Examples of arrangements for mounting samplers behind welder's face shields	21
Annex C (informative) An example of a report.....	28
Annex D (informative) Blank report form.....	31
Bibliography.....	34