

CONTENTS

FOREWORD.....	5
INTRODUCTION.....	7
1 Scope.....	8
2 Normative references.....	8
3 Terms and definitions	9
3.1 General terms	9
3.2 Description of instruments according to their method of operation	13
3.3 Constructional features of instruments.....	14
3.4 Characteristic features of instruments.....	16
3.5 Characteristic values.....	17
3.6 Influence quantity, reference conditions, nominal range of use and preconditioning	17
3.7 Uncertainty and variations	19
3.8 Accuracy, accuracy class and class index.....	21
3.9 Test.....	21
4 Description, classification and compliance.....	22
4.1 Description.....	22
4.1.1 Description according to methods of operation or nature	22
4.1.2 Description according to environmental conditions	22
4.1.3 Description according to mechanical conditions	22
4.1.4 Description according to degrees of protection.....	22
4.2 Classification	22
4.3 Compliance with the requirements of this standard.....	23
5 Requirements	23
5.1 Reference conditions.....	23
5.2 Limits of intrinsic uncertainty, fiducial value	23
5.2.1 Limits of intrinsic uncertainty	23
5.2.2 Correspondence between intrinsic uncertainty and accuracy class	23
5.2.3 Fiducial value.....	23
5.3 Nominal range of use and variations	25
5.3.1 Nominal range of use	25
5.3.2 Limits of variations	27
5.3.3 Conditions for the determination of variations	28
5.4 Operating uncertainty, overall system uncertainty and variations	28
5.5 Electrical requirements.....	28
5.5.1 Electrical safety requirements	28
5.5.2 Self-heating	28
5.5.3 Permissible overloads	29
5.5.4 Limiting range of temperature.....	29
5.5.5 Deviation from zero.....	29
5.5.6 Electromagnetic compatibility (EMC)	29
5.6 Constructional requirements	30
5.6.1 General constructional requirements	30
5.6.2 Damping.....	30
5.6.3 Sealing to prevent access	30
5.6.4 Scales	31

5.6.5	Stopper.....	32
5.6.6	Preferred values	32
5.6.7	Adjusters, mechanical and/or electrical.....	32
5.6.8	Effects of vibration and shock.....	33
5.6.9	Degrees of protection provided by enclosure	33
5.6.10	Terminals.....	34
6	Information, markings and symbols	34
6.1	Information.....	34
6.2	Markings, symbols and their locations.....	35
6.3	Markings relating to the reference values and nominal ranges of use of influence quantities	36
6.4	The symbols for marking instruments and accessories	36
6.5	Markings and symbols for terminals	45
6.5.1	Requirements for markings.....	45
6.5.2	Earthing (grounding) terminals	45
6.5.3	Measuring circuit terminals.....	45
6.5.4	Special markings for terminals.....	45
6.6	Instructions for use.....	45
7	Package	46
8	Test rules	46
8.1	Type of test.....	46
8.2	Type tests	46
8.3	Routine tests.....	46
8.4	Recurrent tests	46
8.5	Nonconformity classification	47
8.6	Judgement of test results	47
Annex A (normative)	Limits of intrinsic uncertainty and variations	48
Annex B (informative)	Relationship between ambient temperature and relative humidity.....	51
Annex C (informative)	Estimation of uncertainties	52
C.1	Uncertainties in this standard	52
C.2	Operating uncertainty	52
C.2.1	General	52
C.2.2	Estimating absolute operating uncertainty according to type test results.....	52
C.2.3	Estimating absolute operating uncertainty according to limit of intrinsic uncertainty and limit of variations due to every influence specified by this standard.....	53
C.3	Overall system uncertainty	54
C.4	Fiducial operating uncertainty.....	54
Annex D (normative)	Routine Tests	55
Bibliography		56
Figure 1	– Measuring range 10 A to 50 A.....	31
Figure 2	– Measuring range 80 V to 110 V.....	32
Figure 3	– Measuring ranges 0,06 MΩ to 0,4 MΩ and 0,1 MΩ to 2 MΩ	32
Figure A.1	– Effect of temperature.....	48
Figure A.2	– Effect of temperature.....	49
Figure B.1	– Relationship between ambient temperature and relative humidity	51

Figure C.1 – Different kinds of uncertainty	52
Table 1 – Minimum IP requirements	22
Table 2 – Reference conditions and tolerances for testing purposes relating to the influence quantities	24
Table 3 – Limits of the nominal range of use and permissible variations	26
Table 4 – The diameters of conductive screw and the diameters or the area of contact surface	34
Table 5 – Units, quantities and SI prefixes	37
Table 6 – Symbols for marking instruments and accessories	38