

Contents

Acknowledgements	xviii
Preface to the fourth edition	xix
Preface to the first edition	xx
Editor's foreword to the first edition	xxii
Editor's foreword to the fourth edition	xxiii
1 Sampling of powders	1
1.1 Introduction	1
1.2 Theory	2
1.3 Weight of sample required	5
1.4 Statistical considerations	7
1.5 Golden rules of sampling	8
1.6 Bulk sampling	9
1.6.1 Stored non-flowing material	9
1.6.2 Stored free-flowing material	9
1.6.3 Moving powders	10
1.6.4 Sampling from a moving stream of powder	10
1.6.5 Sampling from a conveyor belt or chute	13
1.6.6 Sampling from a bucket conveyor	16
1.6.7 Bag sampling	16
1.6.8 Sampling spears	16
1.6.9 Sampling from wagons and containers	19
1.6.10 Sampling from heaps	21
1.7 Slurry sampling	23
1.8 Sample dividing	23
1.8.1 Scoop sampling	25
1.8.2 Coning and quartering	29
1.8.3 Table sampling	29
1.8.4 Chute splitting	29
1.8.5 The spinning riffler	31
1.9 Miscellaneous devices	33
1.10 Reduction from laboratory sample to analysis sample	34
1.11 Reduction from analysis sample to measurement sample	37
1.12 Experimental tests of sample-splitting techniques	38

2	Sampling of dusty gases in gas streams	41
2.1	Introduction	41
2.2	Basic procedures	44
2.2.1	Sampling positions	44
2.2.2	Temperature and velocity surveys	45
2.2.3	Sampling points	46
2.3	Sampling equipment	47
2.3.1	Nozzles	47
2.3.2	Dust-sampling collector	50
2.3.3	Ancillary apparatus	57
2.3.4	On-line dust extraction	57
2.3.5	The Andersen stack sampler	58
2.4	Corrections for anisokinetic sampling	60
2.5	Probe orientation	66
2.6	Radiation methods	67
3	Sampling and sizing from the atmosphere	72
3.1	Introduction	72
3.2	Inertial techniques	76
3.3	Filtration	87
3.4	Electrostatic precipitation	88
3.5	Electrostatic charging and mobility	90
3.6	Thermal precipitation	92
3.7	The quartz microbalance	95
3.8	Optical sensing zone methods	97
3.8.1	Air Technology	102
3.8.2	Atcor Net 2000	102
3.8.3	Bausch and Lomb	102
3.8.4	Beckman	103
3.8.5	Centre for Air Environmental Studies	103
3.8.6	Climet Series 7000	103
3.8.7	Coulter Model 550 contamination monitor	103
3.8.8	Dynac	104
3.8.9	Gardner	104
3.8.10	G.C.A. Miniram	104
3.8.11	Insitec PCSV-P	104
3.8.12	Kratel Partoscope	105
3.8.13	Leitz Tyndalloscope	105
3.8.14	Met One particle counters	105
3.8.15	Pacific Scientific Hiac/Royco particle counting systems	106
3.8.16	Particle Measuring Systems	106
3.8.17	RAC particle monitors	107
3.8.18	Rotheroe and Mitchell digital dust indicator	108
3.8.19	Saab photometer	108

3.8.20	Sartorius	108
3.8.21	Sinclair	108
3.8.22	Techecology	109
3.8.23	TSI particle counters	109
3.8.24	The particulate volume monitor	109
3.9	Condensation nucleus counters	110
3.10	Diffusion battery	110
3.11	The aerodynamic particle size analyser	112
3.12	Miscellaneous techniques	114
4	Particle size, shape and distribution	124
4.1	Particle size	124
4.2	Particle shape	128
4.2.1	Shape coefficients	129
4.2.2	Shape factors	132
4.2.3	Applications of shape factors and shape coefficients	135
4.2.4	Shape indices	140
4.2.5	Shape regeneration by Fourier analysis	141
4.2.6	Fractal dimension characterization of textured surfaces	142
4.3	Determination of specific surface from size distribution data	144
4.3.1	Number distribution	144
4.3.2	Surface distribution	144
4.3.3	Volume distribution	145
4.4	Particle size distribution transformation between number, surface and mass	145
4.5	Average diameters	147
4.6	Particle dispersion	153
4.7	Methods of presenting size analysis data	153
4.8	Devices for representing the cumulative distribution curve as a straight line	156
4.8.1	Arithmetic normal distributions	156
4.8.2	The log-normal distribution	159
4.8.3	The Rosin–Rammler distribution	163
4.8.4	Mean particle sizes and specific surface evaluation for Rosin–Rammler distributions	164
4.8.5	Other particle size distribution equations	164
4.8.6	Simplification of two-parameter equations	165
4.8.7	Evaluation of non-linear distributions on log-normal paper	166
4.8.8	Derivation of shape factors from parallel log-normal curves	169
4.9	The law of compensating errors	170
4.10	Alternative notation for frequency distribution	173
4.10.1	Notation	174

4.10.2	Moment of a distribution	174
4.10.3	Transformation from $q_t(x)$ to $q_r(x)$	174
4.10.4	Relation between moments	175
4.10.5	Means of distributions	176
4.10.6	Standard deviations	177
4.10.7	Coefficient of variation	177
4.10.8	Applications	177
4.10.9	Transformation of abscissa	179
4.11	Phi-notation	181
4.12	Manipulation of the log-probability equation	182
4.12.1	Average sizes	183
4.12.2	Derived average sizes	185
4.12.3	Transformation of the log-normal distribution by count into one by weight	186
4.13	Relationship between median and mode of a log-normal distribution	187
4.14	An improved equation and graph paper for log-normal evaluations	187
4.14.1	Applications	189
5	Sieving	192
5.1	Introduction	192
5.2	Woven-wire and punched plate sieves	193
5.3	Electroformed micromesh sieves	194
5.4	British Standard specification sieves	197
5.5	Methods for the use of fine sieves	198
5.5.1	Machine sieving	199
5.5.2	Wet sieving	200
5.5.3	Hand sieving	202
5.5.4	Air-jet sieving	203
5.5.5	The sonic sifter	204
5.5.6	Felvation	206
5.5.7	Self-organized sieve (SORSI)	207
5.6	Sieving errors	208
5.7	Mathematical analysis of the sieving process	210
5.8	Calibration of sieves	213
6	Microscopy	217
6.1	Introduction	217
6.2	Optical microscopy	217
6.2.1	Sample preparation	219
6.2.2	Particle size distributions from measurements on plane sections through packed beds	221
6.3	Particle size	221

6.4	Transmission electron microscopy (TEM)	223
6.4.1	Specimen preparation	224
6.4.2	Replica and shadowing techniques	226
6.4.3	Chemical analysis	227
6.5	Scanning electron microscopy (SEM)	227
6.6	Manual methods of sizing particles	228
6.6.1	Graticules	229
6.6.2	Training of operators	232
6.7	Semi-automatic aids to microscopy	233
6.8	Automatic counting and sizing	240
6.9	Automatic image analysis	241
6.10	Specimen improvement techniques	243
6.11	Statistical considerations governing the determination of size distributions by microscope count	243
6.11.1	Frequency distribution determination	243
6.11.2	Weight distribution determination	244
6.12	Conclusion	245
7	Interaction between particles and fluids in a gravitational field	249
7.1	Introduction	249
7.2	Relationship between drag coefficient and Reynolds number for a sphere settling in a liquid	251
7.3	The laminar flow region	252
7.4	Critical diameter for laminar flow settling	253
7.5	Particle acceleration	254
7.6	Errors due to the finite extent of the fluid	255
7.7	Errors due to discontinuity of the fluid	257
7.8	Brownian motion	258
7.9	Viscosity of a suspension	261
7.10	Calculation of terminal velocities in the transition region	261
7.11	The turbulent flow region	266
7.12	Non-rigid spheres	266
7.13	Non-spherical particles	267
7.13.1	Stokes' region	267
7.13.2	The transition region	270
7.14	Concentration effects	272
7.15	Hindered settling	278
7.15.1	Low-concentration effects	278
7.15.2	High-concentration effects	279
7.16	Electro-viscosity	280
8	Dispersion of powders	285
8.1	Discussion	285
8.2	Theory of wetting	286

8.3	The use of glidants to improve flowability of dry powders	293
8.4	Density determination	293
8.5	Viscosity	297
8.6	Sedimentation systems	298
8.7	Densities and viscosities of some aqueous solutions	303
8.8	Standard powders	304
9	Incremental methods of particle size determination	310
9.1	Basic theory	310
9.1.1	Variation in concentration within a settling suspension	310
9.1.2	Relationship between density gradient and concentration	311
9.2	Resolution for incremental methods	312
9.3	The pipette method	313
9.3.1	Experimental errors	317
9.4	The photosedimentation technique	320
9.4.1	Introduction	320
9.4.2	Theory	321
9.4.3	The extinction coefficient	323
9.4.4	Photosedimentometers	325
9.4.5	Discussion	327
9.5	X-ray sedimentation	328
9.6	Hydrometers	332
9.7	Divers	335
9.8	The specific gravity balance	336
9.9	Appendix: Worked examples	337
9.9.1	Wide-angle scanning photosedimentometer: analysis of silica	337
9.9.2	Conversion from surface distribution to weight distribution	338
9.9.3	The LADAL X-ray sedimentometer: analysis of tungstic oxide	339
10	Cumulative methods of sedimentation size analysis	344
10.1	Introduction	344
10.2	Line-start methods	344
10.3	Homogeneous suspensions	345
10.4	Sedimentation balances	346
10.4.1	The Gallenkamp balance	349
10.4.2	The Sartorius balance	351
10.4.3	The Shimadzu balance	353
10.4.4	Other balances	353
10.5	The granometer	355

10.6	The micromerograph	356
10.7	Sedimentation columns	356
10.8	Manometric methods	361
10.9	Pressure on the walls of the sedimentation tube	362
10.10	Decanting	362
10.11	The β -back-scattering method	364
10.12	Discussion	365
10.13	Appendix: An approximate method of calculating size distribution from cumulative sedimentation results	366
11	Fluid classification	373
11.1	Introduction	373
11.2	Assessment of classifier efficiency	373
11.3	Systems	379
11.4	Counterflow equilibrium classifiers in the gravitational field – elutriators	380
11.4.1	Water elutriators	382
11.4.2	Air elutriators	386
11.4.3	Zig-zag classifiers	389
11.5	Cross-flow gravity classifiers	390
11.5.1	The Warmain cyclosizer	390
11.5.2	The Humboldt particle size analyser TDS	391
11.5.3	The cross-flow elbow classifier	392
11.6	Counterflow equilibrium classifiers in the centrifugal field	392
11.6.1	The Bahco classifier	392
11.6.2	The BCURA centrifugal elutriator	394
11.6.3	Centrifugal elutriation in a liquid suspension	394
11.7	Cross-flow equilibrium classifiers in the centrifugal field	394
11.7.1	Analysette 9	394
11.7.2	The Donaldson classifier	395
11.7.3	The Micromeritics classifier	397
11.8	Other commercially available classifiers	397
11.9	Hydrodynamic chromatography	398
11.10	Sedimentation field flow fractionation (SFFF)	399
12	Centrifugal methods	405
12.1	Introduction	405
12.2	Stokes' diameter determination	406
12.3	Line-start technique	407
12.3.1	Theory	407
12.3.2	Line-start technique using a photometric method of analysis	407
12.3.3	Early instruments: the Marshall centrifuge and the MSA particle size analyser	410

12.3.4	The photocentrifuge	411
12.3.5	Disc photocentrifuges	413
12.3.6	The cuvette photocentrifuge	415
12.4	Homogeneous suspension	416
12.4.1	Sedimentation height small compared with distance from centrifuge axis	416
12.4.2	The Alpine sedimentation centrifuge	417
12.4.3	The Mikropul Sedimentputer	417
12.5	Cumulative sedimentation theory for a homogeneous suspension	417
12.6	Variable-time method (variation of P with t)	419
12.7	Variable inner radius (variation of P with S)	420
12.8	Shape of centrifuge tubes	421
12.9	Alternative theory (variation of P with S)	422
12.10	Variable outer radius (variation of P with R)	423
12.11	Incremental analysis with a homogeneous suspension	424
12.11.1	The Simcar centrifuge	424
12.11.2	General theory	425
12.12	The LADAL X-ray centrifuge	432
12.13	The LADAL pipette withdrawal centrifuge	435
12.13.1	Theory for the LADAL pipette withdrawal technique	437
12.14	The supercentrifuge	442
12.15	The ultracentrifuge	445
12.16	Conclusion	445
12.17	Appendix: Worked examples	447
12.17.1	Simcar centrifuge	447
12.17.2	X-ray centrifuge	449
12.17.3	LADAL pipette centrifuge	450
13	The electrical sensing zone method of particle size distribution determination (the Coulter principle)	455
13.1	Introduction	455
13.2	Operation	456
13.3	Calibration	457
13.4	Evaluation of results	460
13.5	Theory	461
13.6	Effect of particle shape and orientation	465
13.7	Coincidence correction	466
13.8	Pulse shape	470
13.9	Multiple aperture method for powders having a wide size distribution	474
13.9.1	General	474
13.9.2	Sieving technique	474

13.9.3	Sedimentation technique	474
13.10	Carrying out a mass balance	475
13.11	End-point determination	476
13.12	Upper size limit	477
13.13	Commercial equipment	477
13.14	Conclusions	479
14	Radiation scattering methods of particle size determination	483
14.1	Introduction	483
14.2	Scattered radiation	487
14.2.1	The Rayleigh region ($D \ll \lambda$)	487
14.2.2	The Rayleigh–Gans region ($D < \lambda$)	488
14.3	State of polarization of the scattered radiation	490
14.4	Turbidity measurement	491
14.5	High-order Tyndall spectra (HOTS)	494
14.6	Particle size analysis by light diffraction	495
14.7	Light-scattering equipment	496
14.8	Holography	498
14.9	Miscellaneous	499
15	Permeametry and gas diffusion	503
15.1	Flow of a viscous fluid through a packed bed of powder	503
15.2	Alternative derivation of Kozeny's equation using equivalent capillaries	505
15.3	The aspect factor k	506
15.4	Other flow equations	508
15.5	Experimental applications	512
15.6	Preparation of powder bed	513
15.7	Constant-pressure permeameters	514
15.8	Constant-volume permeameters	519
15.9	Fine particles	521
15.10	Types of flow	522
15.11	Transitional region between viscous and molecular flow	522
15.12	Experimental techniques for determining Z	524
15.13	Calculation of permeability surface	525
15.14	Diffusional flow for surface area measurement	526
15.15	The relationship between diffusion constant and specific surface	528
15.16	Non-steady-state diffusional flow	530
15.17	Steady-state diffusional flow	532
15.18	The liquid phase permeameter	535
15.19	Application to hindered settling	537

16	Gas adsorption	540
16.1	Introduction	540
16.2	Theories of adsorption	541
16.2.1	Langmuir's isotherm for ideal localized monolayers	541
16.2.2	BET isotherm for multilayer adsorption	544
16.2.3	The n -layer BET equation	548
16.2.4	Discussion of BET theory	549
16.2.5	Mathematical nature of the BET equation	551
16.2.6	Shapes of isotherms	553
16.2.7	Modifications of the BET equation	555
16.2.8	The Hüttig equation	556
16.2.9	The relative method of Harkins and Jura (HJr)	556
16.2.10	Comparison between BET and HJr methods	558
16.2.11	The Frenkel–Halsey–Hill equation (FHH)	559
16.2.12	The Dubinin–Radushkevich equation (D–R)	559
16.2.13	The V_A – t method	562
16.2.14	Kiselev's equation	565
16.3	Experimental techniques – factors affecting adsorption	566
16.3.1	Degassing	566
16.3.2	Pressure	567
16.3.3	Temperature and time	567
16.3.4	Adsorbate	567
16.3.5	Interlaboratory tests	568
16.4	Experimental techniques – volumetric methods	569
16.4.1	Principle	569
16.4.2	Volumetric apparatus for high surface area	569
16.4.3	Volumetric apparatus for low surface area	571
16.5	Experimental techniques – gravimetric methods	573
16.5.1	Principle	573
16.5.2	Single-spring balances	573
16.5.3	Multiple-spring balances	574
16.5.4	Beam balances	574
16.6	Continuous-flow gas chromatographic methods	575
16.6.1	Commercially available continuous-flow apparatus	580
16.7	Standard volumetric gas-adsorption apparatus	581
16.7.1	Worked example using BS4359 standard apparatus	583
16.8	Commercially available volumetric- and gravimetric-type apparatus	587
17	Other methods for determining surface area	597
17.1	Introduction	597
17.2	Calculation from size distribution data	598
17.3	Adsorption from solution	599
17.3.1	Orientation of molecules at the solid–liquid interface	599

17.3.2	Polarity of organic liquids and adsorbents	601
17.3.3	Drying of organic liquids and adsorbents	602
17.4	Methods of analysis of amount of solute adsorbed on to solid surfaces	603
17.4.1	Langmuir trough	603
17.4.2	Gravimetric method	604
17.4.3	Volumetric method	604
17.4.4	The Rayleigh interferometer	604
17.4.5	The precolumn method	605
17.5	Theory for adsorption from a solution	605
17.6	Quantitative methods for adsorption from a solution	606
17.6.1	Adsorption of non-electrolytes	606
17.6.2	Fatty acid adsorption	606
17.6.3	Adsorption of polymers	607
17.6.4	Adsorption of dyes	607
17.6.5	Adsorption of electrolytes	609
17.6.6	Deposition of silver	609
17.6.7	Adsorption of <i>p</i> -nitrophenol	609
17.6.8	Other systems	610
17.7	Theory for heat of adsorption from a liquid phase	611
17.7.1	Surface free energy of a fluid	611
17.7.2	Surface entropy and energy	612
17.7.3	Heat of immersion	612
17.8	Static calorimetry	614
17.9	Flow microcalorimetry	615
17.9.1	Experimental procedures – liquids	616
17.9.2	Calibration	618
17.9.3	Determination of the amount of solute adsorbed: the precolumn method	618
17.9.4	Gases	619
17.9.5	Application to the determination of surface area	620
17.10	Density method	620
18	Determination of pore size distribution by gas adsorption	624
18.1	Miscellaneous techniques	624
18.2	The Kelvin equation	624
18.3	The hysteresis loop	627
18.4	Relationship between the thickness of the adsorbed layer and the relative pressure	631
18.5	Classification of pores	633
18.6	The α_s method	634
18.7	Pore size distribution determination of mesopores	634
18.7.1	Modelless method	635
18.7.2	Cylindrical core model	638

18.7.3	Cylindrical pore model	639
18.7.4	Parallel plate model	643
18.8	Analysis of micropores: the MP method	645
18.9	Miscellaneous	649
19	Mercury porosimetry	653
19.1	Introduction	653
19.2	Literature survey	655
19.3	Contact angle and surface tension for mercury	658
19.4	Commercial equipment	658
19.5	Theory for volume distribution determination	663
19.6	Theory for surface distribution determination	665
19.6.1	Cylindrical pore model	665
19.6.2	Modelless method	667
19.7	Theory for length distribution determination	668
19.8	Worked example	668
19.9	Hysteresis	670
19.10	Delayed intrusion	672
19.11	Anglometers	672
19.12	Assessment of mercury porosimetry	674
19.12.1	Effect of experimental errors	674
19.12.2	Effect of interconnecting pores	674
19.12.3	Effect of contact angle	676
19.12.4	Other errors	677
19.13	Comparison with other techniques	677
19.14	Correction factors	678
20	On-line particle size analysis	682
20.1	Introduction	682
20.2	Stream-scanning techniques	683
20.2.1	Brinkmann analyser	685
20.2.2	Climet particle counting systems	685
20.2.3	Flowvision	686
20.2.4	Hiac/Royco (Pacific Scientific) particle counters	686
20.2.5	Horiba particle size analysers	691
20.2.6	The Insitac particle counter	691
20.2.7	Kane May particle size analysers	691
20.2.8	Kratel Partascope	691
20.2.9	Lasentec	692
20.2.10	Met One liquid particle counter	693
20.2.11	Particle Measuring Systems	693
20.2.12	Polytec	694
20.2.13	Procedyne particle size analyser	695
20.2.14	Spectrex Prototron particle counter	696

20.2.15	Talbot optical-electronic method	698
20.2.16	Miscellaneous optical methods	698
20.2.17	Echo measurement	699
20.2.18	The Erdco acoustical counter	700
20.2.19	The Coulter on-line monitor	701
20.2.20	On-line automatic microscopy	703
20.2.21	Comparison between stream-scanning techniques	704
20.3	Field-scanning techniques	704
20.3.1	Some properties of size distributions of milled products	704
20.3.2	Static noise measurement	705
20.3.3	Ultrasonic attenuation measurements	706
20.3.4	β -ray attenuation	711
20.3.5	X-ray attenuation and fluorescence	713
20.3.6	Low-angle laser light scattering	715
20.3.7	Classification devices	719
20.3.8	Hydrocyclones	721
20.3.9	Screening: the Cyclosensor	723
20.3.10	Automatic sieving machines	723
20.3.11	Gas-flow permeametry	727
20.3.12	Pressure drop in nozzles	727
20.3.13	Non-Newtonian rheological properties	728
20.3.14	Correlation techniques	728
20.3.15	Photon correlation spectroscopy	729
	Problems	738
	Appendix 1 Equipment and suppliers	759
	Appendix 2 Manufacturers' and suppliers' addresses	767
	Author index	775
	Subject index	799