

Table of contents

<i>Preface</i>	8
<i>Symbols</i>	10
1. Introduction	18
1.1. Classification of high-speed motors.....	19
1.2. Design issues of high-speed motors.....	19
2. The principle operations of BLDC motors	22
2.1. Simplifying assumptions.....	22
2.2. The classification of motors with permanent magnets	22
2.3. The construction of BLDC motors	22
2.4. Determination of the rotor position.....	24
2.5. The BLDC motor waveforms.....	26
2.5.1. Idealized waveforms.....	27
2.5.2. Real waveforms.....	28
2.6. Equivalent circuits	29
2.6.1. Constant-current equivalent circuit.....	29
2.6.2. Phase equivalent circuit.....	32
2.7. Mechanical equation	35
2.8. Torque-speed characteristics	36
2.8.1. Idealized torque-speed characteristics	37
2.8.2. Real torque-speed characteristics	39
2.9. Cogging torque	39
3. The rotor and the shaft of a high-speed BLDC motor	42
3.1. Mounting of permanent magnets.....	43
3.1.1. Surface mounting.....	43
3.1.2. Interior mounting.....	45
3.2. Layout of magnets.....	45
3.3. Permanent magnets.....	49
3.4. Materials for shafts and rotors of the high-speed motors	51
4. Shaft mechanics	54
4.1. Load bearing capacity of the shaft and fatigue strength calculations	55
4.2. Vibrations of the shaft	61
4.2.1. Lateral vibration	61
4.2.2. Torsional vibrations.....	64
5. The stator of a high-speed BLDC motor	68
5.1. Materials for construction of magnetic cores	68
5.2. Comparison between the three-slot and six-slot design of magnetic cores	71

5.3. Comparison between different types of magnetic cores 71

5.4. Analysis of a slotless magnetic core 77

5.5. Manufacturing technology of magnetic cores made of amorphous materials 80

6. *Bearings*..... 82

6.1. Bearings arrangements 84

6.2. Bearings sealing..... 88

6.3. Main dimensions 90

6.4. Bearing service life 91

6.5. Fitting 101

6.6. Internal clearance and preload 106

6.7. Friction and temperature 112

6.8. Lubrication 115

6.8.1. Grease lubrication..... 118

6.8.2. Oil lubrication..... 121

6.9. Limiting speed 124

6.10. High-speed bearings..... 126

6.11. Other types of bearings..... 130

7. *Control systems* 132

7.1. Inverter 134

7.1.1. Control strategies 138

7.2. DC-DC converters..... 140

7.2.1. Buck converter..... 141

7.2.2. Buck-boost converter..... 142

7.2.3. Forward converter..... 144

7.2.4. Push-pull converter..... 145

7.2.5. Flyback converter 147

7.2.6. Simulation tests of DC-DC converters 148

8. *Sensor based control*..... 150

9. *Sensorless control* 164

9.1. Method based on phase electromotive forces 166

9.2. Method based on the third harmonic..... 168

9.3. Method based on the integration of electromotive forces..... 170

9.4. Method based on phase-to-phase voltages 171

9.5. Motor start-up..... 176

9.6. Sensorless control system 189

10. *Power losses in high-speed BLDC motors* 190

10.1. Power losses in a power electronics device..... 191

10.2. Windings power loss 192

10.3. Magnetic core power loss..... 194

10.4. Bearing power loss	197
10.5. Windage power loss	197
10.6. Rotor power loss.....	200
10.7. Stray power loss	202
11. Examples of high-speed motor designs.....	204
11.1. Overview of worldwide high-speed motor designs.....	204
11.2. Polish high-speed motor designs.....	212
11.2.1. High-speed motor prototype with a speed of 60,000 rpm.....	213
11.2.2. Open structure prototype	214
11.2.3. Slotless prototypes.....	216
11.2.4. Closed slots prototype	217
11.3. Power losses and efficiency analysis for a high-speed motor	218
References	224
Abstract.....	238