

Contents	Page
Foreword	iv
Introduction	v
1 Scope	1
2 Normative references	1
3 Terms and definitions	1
4 Classification	2
5 Requirements	2
5.1 General	2
5.1.1 Design	2
5.1.2 Connection	2
5.1.3 Operating controls	3
5.1.4 Cleaning, disinfection and sterilization	3
5.1.5 Excessive temperatures	3
5.2 Radiant exitance	3
5.2.1 Radiant exitance in the 380 nm to 515 nm wavelength region	3
5.2.2 Radiant exitance in the wavelength region below 380 nm	3
5.2.3 Radiant exitance in the wavelength region above 515 nm	3
5.3 Electrical safety requirements	3
5.4 Physical and mechanical safety	4
5.5 Usability	4
5.6 Instructions for use manual	4
5.7 Technical Description	4
5.8 Marking	4
5.9 Packaging	4
6 Sampling	4
7 Measurement and test methods	4
7.1 General	4
7.1.1 General provisions for tests	4
7.1.2 Atmospheric conditions	5
7.2 Inspections	5
7.2.1 Visual inspection of powered polymerization activator	5
7.2.2 Manual inspection of powered polymerization activator	5
7.2.3 Visual inspection of manufacturer's document	5
7.3 Measurement of the optical cross-sectional area of the light guide/light-emitting tip	5
7.3.1 Apparatus	5
7.3.2 Procedure	5
7.4 Measurement of radiant exitance	5
7.4.1 Method A using spectrometer	5
7.4.2 Method B using filters	8
8 Information (instructions for use) to be supplied by the manufacturer	12
9 Marking	13
10 Packaging	14
Bibliography	15