

Contents

Page

Foreword4

Introduction.....5

1 Scope6

2 Normative references6

3 Terms and definitions6

4 Glass products7

5 Fracture characteristics7

6 Dimensions and tolerances.....7

6.1 Nominal thickness and thickness tolerances7

6.2 Width and length (sizes).....8

6.2.1 General8

6.2.2 Maximum and minimum sizes.....9

6.2.3 Tolerances and squareness9

6.2.4 Edge deformation produced by vertical toughening.....10

6.3 Flatness11

6.3.1 General11

6.3.2 Measurement of overall bow11

6.3.3 Measurement of local bow13

6.3.4 Limitation on overall and local bow.....13

7 Edge work, holes, notches and cut-outs.....14

7.1 Warning14

7.2 Edge working of glass before toughening14

7.3 Profiled edges15

7.4 Round holes15

7.4.1 General15

7.4.2 Diameter of holes15

7.4.3 Limitations on position of holes15

7.4.4 Tolerances on hole diameters.....17

7.4.5 Tolerances on position of holes17

7.5 Notches and cut-outs18

7.6 Shaped panes.....18

8 Fragmentation test.....19

8.1 General19

8.2 Dimensions and number of test specimens19

8.3 Test procedure19

8.4 Assessment of fragmentation20

8.5 Minimum values from the particle count.....20

8.6 Selection of the longest particle21

8.7 Maximum length of longest particle21

9 Other physical characteristics21

9.1 Optical distortion21

9.1.1 Thermally toughened alkaline earth silicate safety glass produced by vertical toughening21

9.1.2 Thermally toughened alkaline earth silicate safety glass produced by horizontal toughening21

9.2 Anisotropy (iridescence)21

9.3 Thermal durability21

9.4 Mechanical strength22

9.5	Classification of performance under accidental human impact.....	22
10	Marking.....	22
Annex A (informative) Curved thermally toughened alkaline earth silicate safety glass.....		23
Annex B (informative) Example of particle count		24

Figures

Figure 1	— Examples of width, B , and length, H , relative to the pane shape	8
Figure 2	— Tolerance limits for dimensions of rectangular panes.....	9
Figure 3	— Tong mark deformation	10
Figure 4	— Representation of overall and local bow	12
Figure 5	— Support conditions for the measurement of overall bow.....	13
Figure 6 a)	— Arrissed edge (with blank spots)	14
Figure 6 b)	— Ground edge (with blank spots).....	14
Figure 6 c)	— Smooth ground edge (no blank spots)	15
Figure 6 d)	— Polished edge.....	15
Figure 7	— Relationship between hole and edge of pane	16
Figure 8	— Relationship between two holes	16
Figure 9	— Relationship between hole and corner of pane	17
Figure 10	— Examples of the positioning of holes relative to the datum point.....	18
Figure 11	— Examples of notches and cut-outs	18
Figure 12	— Position of impact point.....	19
Figure 13	— Area to be excluded from the particle count determination and largest particle measurement.....	20
Figure 14	— Examples of crack-free particles and the assessment regarding the number	20
Figure B.B1	— Select the area of coarsest fracture, place the template on the test specimen and draw round the template	24
Figure B.B2	— Mark and count the perimeter fragments as 1/2 particle each.....	25
Figure B.B3	— Mark and count the central fragments and add these to the perimeter count to obtain the particle count for the specimen	26

Tables

Table 1	— Nominal thicknesses and thickness tolerances	8
Table 2	— Tolerances on width, B , and length, H	10
Table 3	— Maximum values for overall and local bow.....	14
Table 4	— Tolerances on hole diameters.....	17
Table 5	— Minimum particle count values.....	21
Table 6	— Values for the mechanical strength of thermally toughened alkaline earth silicate safety glass.....	22